MONADNOCK REGIONAL SCHOOL DISTRICT

FACILITY AND SPACE NEEDS ASSESSMENT STUDY

OCTOBER 31, 2019



TABLE OF CONTENTS

Table of Contents
Purpose and Assumptions1
Purpose 1
Assumptions 1
Existing Conditions1
Building and Life Safety Codes and
Department of Education Rules 1
Enrollment Projections2
Program Data2
Costs
Expectations3
Building Needs Analysis4
Cutler
General Observations5
Site and Exterior
Building and Life Safety Code 5
Indoor Environmental Quality 6
Interior Finishes
Security and Safety6
Emerson
General Observations
Site and Exterior
Building and Life Safety Code7
Indoor Environmental Quality7
Interior Finishes
Security and Safety8
Gilsum
General Observations
Site and Exterior
Building and Life Safety Code 8
Indoor Environmental Quality9
Interior Finishes9
Security and Safety9
Mt Caesar
General Observations 9
Site and Exterior
Building and Life Safety Code9
Indoor Environmental Quality 10
Interior Finishes10
Security and Safety
Troy
Site and Exterior
Building and Life Safety Code 10
Indoor Environmental Quality 11
Indoor Environmental Quanty 11 Interior Finishes 11

Security and Safety	11
Program Analysis	
Enrollment Projections	
Capacity Calculations	
Space Needs	
General Observations	
Cutler	14
General Observations	14
Educational Space	14
Core Space	14
Emerson	14
General Observations	14
Educational Space	15
Core Space	
Gilsum	
General Observations	15
Educational Space	15
Core Space	15
Mt Caesar	15
General Observations	15
Educational Space	15
Core Space	
Troy	16
General Observations	16
Educational Space	16
Core Space	16
Conclusions	17
Planning	17
Options	17

Appendices:

Existing Conditions Analysis

List of Tables:

Chart A – Enrollment Graphs

For each building:

Cutler Emerson Gilsum Mt Caesar Troy

Table A – General Conditions
Table B – LSC 101 Code Review
Table C – IBC Code Review
Table D – Building Needs

Table E - Curriculum Table F - Space Needs

List of Drawings:

For Each of:

Cutler

Emerson

Gilsum

Mt Caesar

Troy

EX1 – Existing Site Plan

EX2 – Code Review Plan

 $EX3-Usage\ Plan$

Recommendations

Chart B – Options Matrix

For each option and building:

Cutler Emerson Gilsum Mt Caesar Troy

Table G – Bond Estimate
Table H – Life-Cycle Cost

PURPOSE AND ASSUMPTIONS

PURPOSE

The charge of this study is to analyze the building and space needs of the elementary schools of the Monadnock Regional School District and suggest alternatives with associated costs. These schools include the schools in the towns of Fitzwilliam, Gilsum, Swanzey and Troy. The intent is to create a comprehensive, broad picture analysis of the building for use in future planning. Further design and planning will be needed for developing the project and getting public approval. The report will simply provide the statement of need and basic data for beginning that work.

This report covers the school buildings in the Monadnock Regional School District including:

- Mt Caesar Elementary School
- Cutler Elementary School
- Dr. George S. Emerson Elementary School
- Gilsum STEAM Academy
- Troy Elementary School

Final decisions on building options will need to rely heavily on public input to fully understand opportunities and constraints that face this district.

ASSUMPTIONS

Existing Conditions

The buildings were visited at various times throughout 2019. Original drawings documenting a large part of the existing buildings were obtained. Actual dimensions were not verified due to the volume of space studied. Inaccuracies were noticed in some drawings, but these issues do not affect the outcome of the study. Verification of existing conditions should be part of any final plan.

Building and Life Safety Codes and Department of Education Rules

The work outlined is based on the following codes; The 2015 NFPA 101 Life Safety Code, The State Building Code (2015 International Building Code, 2015 International Existing Building Code, 2015 Mechanical Code, 2017 National Electric Code, and others), The State Energy Code and The State Barrier Free Access Code. Because of

the generalized scope of the study it is not possible to list every possible item that falls within these codes. It is assumed that any areas impacted by proposed changes would have all code issues resolved.

There is often a misconception that code compliance problems are "grandfathered" if they have existed for a long time. The State of NH Department of Education Administrative Rules (ED 306.07) requires all approved schools to meet NFPA 101 Life Safety Code as well as other codes. Other codes such as the State of NH Fire Code and the State of NH Building Code refer to this code as well thus giving local code enforcement officers the authority to require upgrades regardless of how long the situation has existed. However, it happens quite often that review for compliance is not done until a major construction project is proposed.

Chapter 15 of NFPA 101 is specifically designed for existing educational facilities. We suggest that the local authorities as well as the State Fire Marshal's office be invited to walk through the building and review this study to ensure that the District fully understands what is required.

Enrollment Projections

Understanding anticipated enrollments is the first step in understanding the function of a school facility. As important to the calculations as the total number of students are the individual class sizes. It is possible for a school facility to reach maximum capacity long before the stated capacity if one year's enrollment is much larger than others. One large cohort of students will put stress on the core facilities as if the entire school where much larger. It is therefore important to design the core facilities for a larger number of students than simply the anticipated total.

This report includes enrollment projections based on data provided by the District. Actual enrollments can be significantly different and should be monitored each year. The projections are a tool for identifying trends that are useful in determining design parameters.

Program Data

It is important to analyze the building usage in order to determine areas that might require changes to improve the function of the building. The first step in identifying space needs is to develop the program or a list of spaces and their correlating size. To do this we rely on several sources including; NH Department of Education Standards, Association for Learning Environments (formerly; Council for Educational Facility Planners Inc.), other State Standards, examples of other similar projects and our own experience.

We also, possibly more importantly, rely on the Owner to supply us information for their programs. This was collected by interviewing the Principal and by analyzing how the building is currently used. This data includes; enrollment per course, periods per day, meetings per week and other information. Changes in this data would therefore change the results in this report.

It is also important to note that we did not always use the "minimum" standards when analyzing the data. Class size in particular can greatly affect the space needs of a

school. Current trends are to limit class sizes. For this study we used numbers that were neither the absolute maximum nor minimum but rather, closely match the average for schools in the state of NH.

Costs

There are several sources that we rely on for cost data. RS Means is a construction cost index that helps establish a range of costs. Other similar projects are also used. For a report with this broad a scope, however, it is not possible to produce accurate estimates due to the level of detail. Also that cost data is almost immediately outdated due to inflation. We have prepared this report based on an average cost per square foot per task. This will give us an "Order of Magnitude" estimate on cost for determining budgets.

New construction costs are based on the NH Department of Education cost per square foot maximum cap. This helps establish the benchmark for the limit any project generated from this report needs to meet. It is not meant as a final construction estimate.

All costs are given in "today's numbers". Inflation for building materials is very difficult to forecast. At the time of this report, many resources are seeing increased inflation. The costs in this study will need to be verified before proceeding with a construction project.

Expectations

As with any renovation project there are areas that will be left undone. It is not economically feasible to upgrade every aspect of an older building to meet the same criteria of new construction. It is important to set limits on expectations to avoid an endless amount of project growth.

BUILDING NEEDS ANALYSIS

This section studies the existing facility for deficiencies relating to the building or property. Most data were obtained from previous studies and additional data was generated from site visits, interview with staff and extracted from original drawings.

Overall, the district schools have some similar traits. All have had multiple additions over the decades. This has created floor plans that developed very organically and not with long-term planning in mind. There are many awkward or poorly utilized spaces that lowers the overall building efficiency. Many spaces have been repurposed from the original intent but not with the greatest success. This functional obsolescence is typical in any older educational facility but is particularly severe here.

Security in schools is currently a very hot topic. Since Columbine we have been designing schools to be more secure. Before Columbine there was little worry about the public accessing school facilities, but we have since learned that this is a substantial problem. Although we plan for the worst-case event with a shooter entering the building, there are many smaller instances of security breaches in schools that do not become headline news but are still very important to prepare for. All schools should have a secure entrance with a direct connection to the main office. Few of the schools in the MRSD have this in place.

Many of the schools have many exit doors. These were probably installed for life safety purposes but over the years many are not used or no longer have proper hardware or exit discharge to be used as such. The effect is no perceptible increase in life safety but a significant decline in security since each exit also represents a possible point of entry. This reviewer found at least one instance of a door left unlocked after school hours.

It is worth noting that all the district facilities are clean and well maintained. The staff obviously put pride into the buildings, and this helps with the value of education provided. This intent of this report however is to point out the deficiencies and this should not be misconstrued with criticism of the staff.

Mt Caesar has recently gone through a renovation/addition project. Although some deficiencies remain, overall this school is the closest to an acceptable level of condition and will be used by this study as the standard by which all facilities will be graded. All the schools are fully sprinklered which is very important and helps with many code issues.

Items identified are cataloged with costs listed by priority. High priority items are those that need to be done within the next two years. They include issues such as code deficiencies or maintenance items that could cause damage if left undone. Medium priority items should be completed within five to ten years. They are important but do not pose an immediate need. Low priority items are worth considering due to cost savings or improved efficiency. They could be done at any time and often can be done more cost effectively if combined within a larger project.

CUTLER

General Observations

Cutler Elementary School is typical of the elementary schools in the Monadnock Regional District. The original building is an older, small wood framed schoolhouse and over the decades has received multiple additions with the original now just a small part of the overall school and no longer the focus point. The complex is sprawling and at times feels disjointed. The front entrance is not the obvious original front entrance but rather a very understated doorway on the side alley. The gymnasium has its own entrance along that alley. The entrance door between the portable classrooms is the most accessible entrance but this is the furthest from any administrative space.

Site and Exterior

Cutler sits on a very small piece of property but utilizes adjoining town land. The building is tight to property lines on two sides making an addition difficult. The typography is flat. The drop-off/pick-up for cars and buses are not well laid out. The driveway for the buses is narrow and has resulted in buses having collided with the building. The driveway for the cars is short and provides little queuing space and blocks parking spaces when in use.

The exterior has numerous needs. The fire escape stairs do not meet code for exit discharge. The last addition has a significant amount of mold on the split-faced concrete block. This is caused by moisture. The source of this should be investigated and the mold cleaned. Many of the windows need replacement.

Most of the exterior masonry joints need to be resealed. Some appear to have opened up meaning there could be movement in the wall. This does not appear to be structural but should be monitored.

Building and Life Safety Code

The original building with the early 3-story addition does not meet code in several ways. The top floor does not have a valid second means of egress. The fire escape stair, while possibly to code when installed, is old and not to current standards. The stair that serves this floor has breaches in the fire rating and discharges back into the building, not to the exterior. The corridors need to be resistant to the passage of smoke and the stair needs to be fire rated. Some doors have holes that compromise this.

The handicap accessibility is provided by a stair lift which is a hazard for egress and not a proper means of supplying accessibility. There are numerous exterior doors that at one time were provided for egress but that no longer function well or safe per current standards.

The building is essentially three separate buildings for code review; the original with the early 3-story additions, the 1-story classroom and gymnasium addition and the 2 portable classrooms. The portable classrooms, although meeting code, are not the same quality as the other two buildings and should probably be removed.

The toilet facilities are largely not code compliant and do not provide an adequate number of fixtures to meet building code. The main problem with quantity being the lack of fixtures for assembly in the gymnasium.

Indoor Environmental Quality

The ventilation is primarily delivered through unit ventilators. This type of system was common when the building was first constructed but is no longer considered appropriate for schools due to noise and inefficiency. An entirely new system is recommended

The control system for the heating and cooling is mostly archaic. It does not allow for effective monitoring and control. A new digitally controlled system would allow for more efficient operation of the systems and produce data that can be used to trouble-shoot problems. There is just limited air conditioning for the facility.

Many of the light fixtures are due to be replaced. This would also give the opportunity to install much more efficient and better-quality lighting such as indirect dimmable LED's.

Interior Finishes

The interior finishes are in various stages of wear with most needing some attention. The flooring needs to be replaced in large areas of the building. The walls are drywall and show wear. The ceilings are mostly drywall with mechanical and electrical systems exposed. The ceilings that are suspended ceilings have fiberglass tiles which are residential in quality and show wear.

Security and Safety

The main entrance does not have a secure vestibule. Rearranging of the administrative offices to get the reception connected to the entrance should be considered. The gym can be locked off for public use but an even more secure arrangement should be considered.

EMERSON

General Observations

Emerson Elementary School is typical of the elementary schools in the Monadnock Regional District. The original building is an older, small wood framed schoolhouse. Over the decades it has received multiple additions and now the original is a small part of the overall school and no longer the focus point. The community shows strong support for the school and it is well maintained. Many of the components however are showing serious wear and age.

Site and Exterior

Emerson sits on 16 acres of land and has generous space for buildings, driveways and play areas. The typography is gently sloped. The current layout for car and bus drop-off/pick-up seems to work but could be improved.

Because of the various ages of the building there are various needs depending on the area in question. On the exterior there is a need for new windows and new roofs in certain areas.

Building and Life Safety Code

The facility is mostly up to current codes however there are some areas in need of improvement. The original building does not meet several aspects of the code. The lower level has several deficiencies. This area is relatively small and a better solution to upgrading this area might be to relocate the programs housed there to a code compliant section of the building.

The building is mostly wood framed and structurally in reasonable shape. The structure was not designed and built under today's codes, therefore may not meet many current code requirements. The buildings however do not show significant deflection or failure therefore do not require immediate repair. However, if a major addition were to be contemplated, the existing buildings would need to be analyzed for any changes in load that it might receive.

The toilet facilities are largely not code compliant and do not provide an adequate number of fixtures to meet building code. Renovating and possibly expanding the toilet facilities is recommended.

Indoor Environmental Quality

The ventilation is primarily delivered through unit ventilators. Some have been replaced but many are original. This type of system was common when the building was first constructed but is no longer considered appropriate for schools due to noise and inefficiency.

The control system for the heating and cooling is mostly archaic. It does not allow for effective monitoring and control. A new digitally controlled system would allow for more efficient operation of the systems and produce data that can be used to trouble-shoot problems. There is just limited air conditioning for the facility.

Many of the light fixtures have received recent upgrades, however this technology is rapidly changing, and further upgrades could be warranted. This would also give the opportunity to install much more efficient and better-quality lighting such as indirect dimmable LED's.

The intercom system is relatively new. It may be worth considering an integrating the system with the other elementary schools.

Interior Finishes

The interior finishes are in various stages of wear with most needing some attention. The ceilings in the older parts of the building are in poor shape and need to be replaced. Some areas of the 1970's wing should receive new floor tile. The doors in the older parts of the building are delaminating and starting to splinter. Some rooms should receive additional cabinetry.

Security and Safety

The main entrance does not have a secure vestibule. Rearranging of the administrative offices to get the reception connected to the entrance should be considered. The gym can be locked off for public use, but an even more secure arrangement should be considered.

GILSUM

General Observations

Gilsum STEAM Academy has a somewhat unique design compared with the rest of the schools in the district. First, it is the smallest with the smallest enrollment. Secondly, the gymnasium and cafeteria is considered the town community center. The design of the community center is attractive, but the arrangement and the existence of a courtyard poses challenges.

Site and Exterior

The site provides enough space for parking and play areas. It has areas of steep slopes and does not allow for access around the entire facility. There is no separation of car and bus traffic. The exterior of the building has some wear, but general maintenance will take care of most of the problems. The courtyard can be an attractive area but also a nuisance for maintenance, snow removal and the inevitable removal of the oil tank. Probably most importantly, the main entrance to the school is inside the courtyard with the main entrance for the community center closer to the parking.

Building and Life Safety Code

The facility has a few issues with code. The kindergarten classroom is over 1,000 square feet and therefore is required to have two separate means of egress. Due to the slope of the grade outside the classroom it is not feasible to have an exterior exit door. There is an interior door to the adjoining classroom, but the intervening room exit is not remote from the kindergarten exit making that door non-compliant. Otherwise, the schools small size helps to evacuate the occupants quickly.

The building is mostly wood framed and structurally in reasonable shape. The structure was not designed and built under today's codes, therefore may not meet many current code requirements. The buildings however do not show significant deflection or failure therefore do not require immediate repair. However, if a major addition were to be contemplated, the existing buildings would need to be analyzed for any changes in load that it might receive.

The toilet facilities are not all code compliant and do not provide an adequate number of fixtures to meet building code. The toilet facilities for the assembly space are undersized but do meet ADA. The main gang toilets are not handicap accessible. Renovating and possibly expanding the toilet facilities is recommended.

Indoor Environmental Quality

The ventilation is primarily delivered through unit ventilators that existing in most classroom. Some have been replaced but many are original. This type of system was common when the building was first constructed but is no longer considered appropriate for schools due to noise and inefficiency.

The control system for the heating and cooling is mostly archaic. It does not allow for effective monitoring and control. A new digitally controlled system would allow for more efficient operation of the systems and produce data that can be used to trouble-shoot problems. There is just limited air conditioning for the facility.

The light fixtures are largely fluorescents and an upgrade to LED's would save on energy. Additionally, LED's can be dimmable and provide much better-quality lighting than fluorescent or incandescent lights.

The intercom system is archaic and should be replaced. It may be worth considering an integrated system with the other elementary schools.

Interior Finishes

The interior finishes are in various stages of wear with most needing some attention. The ceilings throughout everywhere but the community center need to be replaced. There is a possibility of floor tiles containing asbestos to exist in the building. This should be abated, and the flooring replaced.

Security and Safety

The main entrance is deep inside the courtyard and not visible from the parking lot. Most visitors probably use the entrance to the community center which means that by the time they reach the main office they have mixed with students. A means of getting visitors to enter directly into the main office should be implemented.

MT CAESAR

General Observations

Mt Caesar has had recent renovations and additions and therefore is the most up-todate facility with the fewest issues. That said, there are some needs to be addressed.

Site and Exterior

The site is the largest of all the elementary schools in the district. It is located near the Middle/High School and SAU. The typography is flat with ample room for expansion. The driveways and parking are being studied for improvement.

Building and Life Safety Code

There are a few small code issues. One kindergarten classroom and the preschool classrooms are over 1,000 square feet and required a second means of egress. There is an interior door to the adjoining classrooms, but the intervening room exit is not remote

from making that door non-compliant. One classroom lacks the proper width for its entrance door.

The toilet facilities are not all code compliant and although there appears to be close to the necessary quantity of fixtures, there is not enough for assembly use. Since the cafeteria is not a true assembly space this might not be a large problem. Toilet facilities for the lower grades, particularly the kindergarten is recommended.

Indoor Environmental Quality

The entire ventilation system has been recently upgraded and performing well. Lighting is likewise all new.

Interior Finishes

The interior finishes are mostly new. There are some remaining areas that have not been fully renovated.

Security and Safety

The main office is remote from the main entrance. This is a serious problem that should be addressed.

TROY

General Observations

Troy has had the fewest in additions and renovations and in some ways has benefited from this but in many other tends to suffer. The positive is that the layout is close to the original design intent, but the negative is that many issues that have developed over time are left unaddressed.

Site and Exterior

The site is large in acreage but only a small portion is usable. The topography immediately around and to the west is relatively flat and open but at the edge of the pavement the land slopes dramatically away. This leaves little opportunity for expansion. The original building is 3-stories which keeps the footprint relatively small for the amount of space and helps with site issues. There is a separate bus drop-off/pick-up area, but car pick-up\drop-off is less well defined.

The main entrance is not easily identifiable and not secure.

The superstructure is in relatively good shape for the age but many less durable components such as the roof, windows and doors need replacement.

Building and Life Safety Code

The facility has a numerous code issues. The original building has two stairs connected which was typical for the vintage construction. These were often design for separating boys and girls and not meant for separate egress. Current code requires that every level

must have legitimate fire rated exits and these stairs do not provide that. Some rooms have their own exit to the exterior but some, particularly on the upper levels are suspect on how safe they are.

Kindergarten and 1st Grade are limited to Levels of Exit Discharge unless the space is provided its own dedicated exit. This includes special education or core facilities where there is more than one student per teacher. Some rooms do not meet this.

The building is masonry bearing walls with wood framing. It was good quality at the time of construction but is unlikely to meet current structural code for issues such as seismic loads.

The building is not fully handicap accessible. The main entrance has stairs and there are multiple stairs and ramps inside the building. There is a stair lift to some spaces but not elevator. The toilet facilities are not handicap accessible.

Indoor Environmental Quality

The ventilation is archaic and in need of replacement. The control system for the heating and cooling is archaic if almost non-existent. This does not allow for effective monitoring and control. A new digitally controlled system would allow for more efficient operation of the systems and produce data that can be used to trouble-shoot problems. There is just limited air conditioning for the facility.

The light fixtures are older and inefficient. Upgrading to dimmable LED's would provide more energy efficient and much better-quality lighting.

The intercom system is archaic and should be replaced. It may be worth considering an integrated system with the other elementary schools.

Interior Finishes

The interior finishes are mostly in need of replacement. The ceilings throughout the facility but most notably in the gymnasium need to be replaced. Some walls are still lath and plaster and should be replaced. Other issues include bringing the casework and equipment up to district standards.

Security and Safety

The main entrance is not secure. Although there is an office near the entry door, visitors have access to the school once through the main doors. The location does not provide good visibility to the staff of visitors approaching the building.

PROGRAM ANALYSIS

Programs have changed over the years and older buildings can become inefficient without modifications. Additions often exacerbate the problem by prohibiting building components from functioning the way they were originally meant.

The elementary schools in the Monadnock Regional School District are a good example of this. All the facilities have had numerous additions, and these have created some awkward spaces. Many rooms have been cooped from a previous use to a new use as the education style has changed. Many newer problems in schools such as safety and security have resulted in the improper placement of building elements such as a secure front entrance and main office.

Enrollment Projections

The first step in preparing space needs recommendations is to determine the number of students the building will be designed to serve. Enrollments are predicted in this report using a nomothetic calculation or an estimate based on probability. For this study we used a cohort survival enrollment projection. Historic enrollments and births are used to calculate the likelihood of future students moving in or out of the district. Figures are calculated using a 5-year average, 3-year weighted average and simple projection. Creating projections beyond what is available for data is unreliable. Therefore only 5 years worth of enrollments are reliable for the elementary school level which reflects the available birth data.

The difficulty in preparing enrollment projections is determining probable future enrollments for kindergarten. Once that is established tracking the progression of students through the grades is more set. Many school districts throughout New Hampshire have experienced a drop in enrollments due to low birth rates. Demographics show that Millennials are now the largest living generation. Millennials are having fewer children and having them later in life. They are just reaching the age where their children are starting to attend school. This means that there could be a flattening of the decline seen in recent years and possibly a slow incline in enrollments starting soon and into the foreseeable future.

Economic factors also play an important role in enrollments. The towns that make up the Monadnock Regional School District have a lower median income that the average town in New Hampshire. This may make the area attractive for residence looking for low-cost housing but can drive away upwardly mobile young professionals looking for quality schools. This is demonstrated by a sharp decline in historic enrollments in the 3rd and 4th Grades. This hits Swanzey and Fitzwilliam relatively hard.

Another difficulty in preparing enrollment projections is the small class size per school. A small deviation in the data can cause a large and inaccurate deviation in the results. This shows most in Gilsum where the class sizes are the smallest.

For the purposes of this study the design capacity of each school will be set as the current enrollments indicate with some adjustment for possible spikes in the future. The enrollments and birth rates should be closely monitored for changes. For now the projections show a decline for the foreseeable future therefore additional capacity is not warranted.

Capacity Calculations

Once a target capacity is determined using the enrollment projections the number of teaching stations is calculated (Table E – Curriculum Worksheet). The target capacity is represented by two numbers: the design capacity and the core capacity.

The design capacity is defined as the number of students that the building design will accommodate and function normally. The design capacity uses the average amount of students in each of the classrooms to generate an overall picture of the functionality of the school. It is possible that the school could exceed the designated design capacity but with every additional student there would be some decrease in the quality of education.

The core capacity is defined as the number of students that the core areas of the building will accommodate and function normally even with peak years and future growth factored in. The core areas are further defined as the spaces that all students in all the grades use to some degree. They include the gymnasium, library, main office, cafeteria, and other similar areas. These areas need to be designed to accommodate the peak number of students possible in any one particular grade or grouping. The effect is that the core capacity needs to be a higher amount than the design capacity to handle anomalies that invariably occur in enrollments.

The design capacity is divided into groups representing individual grades and/or by curriculum depending on grade level. The average class size, the number of meetings per week and a utilization rate all factor into the total number of rooms required. From this data a core capacity is established using a maximum room capacity multiplied by the number of teaching stations.

The utilization rate represents unutilized space that is necessary to schedule activities and otherwise allow a school to function smoothly. Utilization rates at elementary schools can be as high as 90% while at middle and high schools where students change class throughout the day the utilization rates are usually as low as 85% or 75%.

Space Needs

The Space Needs Worksheets (Table F) utilized the capacity calculations to create a program of space required for each building. The number of teaching stations is multiplied by the required space for each. The net of the program areas is multiplied by a factor that represents non-program space such as corridors, toilet rooms, thickness of walls, and other miscellaneous areas.

This creates a snapshot of the school if that school were to be built new. This is compared to the actual spaces. Program deficiencies and inadequacies in space need can then be identified.

General Observations

Each elementary school in the Monadnock Regional School District is somewhat unique in how the program is worked out in its facility. All have become somewhat sprawling in the layout which can have adverse effects on security, supervision, ergonomics and collaboration. The classrooms themselves are different sizes and

shapes with many not meeting the NH Department of Education standards. These variations can create situations where one student's experience is very different from one school to the next or even from one classroom to the next.

Some schools practice multi-age classrooms to be able to better utilize available space. This standard however is not universally practiced, even within the same school. This seems to be driven from a space-needs pressure, not driven by education quality.

Swanzey students are shared between Mt Caesar (PK-2) and Cutler (3-6). These two are the only two schools in the district that do that. This helps with leveling the class size but also means that students that attend here have an extra transition than other towns. This may help to explain the large drop in enrollments in Swanzey for grade 3 and grade 4.

The library appears to be almost an afterthought in all the schools. Libraries have changed in the last few decades and now rely more on technology than they have in the past. Even such, libraries perform an important role of being a hub for the school they serve. This does not seem to exist in the Monadnock Regional School District.

The challenge here is to provide a means of leveling the design of each school to standard that allows a reasonably equal quality of education to every student.

CUTLER

General Observations

Cutler is a good example of an organically developed floor plan that has lost good planning. Core facilities are spread throughout the building making access and supervision less efficient. The library is in the basement area and not easily utilized after hours. The principal is not connected with the main office. Special Education is largely also in the basement which does not work well with inclusion.

Educational Space

Most regular classrooms are adequate in size but do range from a low of 650 square feet to just about 900 square feet. Art and Music share a space that is 830 square feet which is small for that program.

Core Space

Core spaces are reasonably adequate in size for the design capacity but again, are not well organized.

EMERSON

General Observations

Emerson likewise developed very organically. The main office suite is at one end of the building, near but not directly connected with the main entrance. Many of the corridors have spaces only on one side meaning corridors are longer and take up more space than a typical school.

Educational Space

Most regular classrooms are adequate and uniform in size close to the 900 square foot target.

Core Space

Core spaces are reasonably adequate in size with the library the one exception. The library is in a below-grade space in the original building. This is not very appropriate because it does not give good access to students.

GILSUM

General Observations

Gilsum is the smallest school in the district but has received many additions over the years. The main office suite is in the central part of the building, which is good for supervision, but it is not directly connected with the main entrance which is bad for security.

Educational Space

The classrooms vary in size but are on average quite large. They are also multi-age classrooms, so the extra size is important. The number of classroom work for the current enrollments but would not work at a higher capacity.

Core Space

The gymnasium and cafeteria are large for the design capacity and it is odd that this school, which is the smallest in the district, is the only school with both. The library and offices are small.

MT CAESAR

General Observations

Mt Caesar is the school that has had the most attention for renovations and additions but is no better organized in terms of program.

Educational Space

The Kindergarten classrooms vary in size from 1023 square feet down to 633 square feet which is considerably lower than the NH Department of Education standard of 1,000 square feet. Regular classrooms vary less with the average just about at the state recommendation of 900 square feet. This the only school with separate art and music.

Core Space

There does not exist a true gymnasium here. The multi-purpose room is too small for physical education and serves primarily as a cafeteria. Administration is close to the center of the building but is separated from the main entrance by the boiler room. The

library is in a former classroom and is located in the center of one of the classroom wings.

TROY

General Observations

Troy has most of the program spaces in the original 1890's schoolhouse. This model worked well at the time and can work well again but currently has some challenges. The addition is not well integrated into the original building making communication between the space awkward.

Educational Space

The classrooms are small. Another problem seems to be adjacencies. The preschool is in a small classroom and adjacent to the 1st Grade classroom which is remote from the other 1st Grade rooms.

Core Space

The core facilities appear to be adequate in size with notable exceptions being the kitchen o and the library. Again, another problem is adjacencies with spaces such as the nurse not being centrally located.

CONCLUSIONS

PLANNING

There are questions to consider that involves much more than "How many students?" and "How much will it cost?". Each community needs to consider the benefits and concessions of future plans. Core at this is the question of "Neighborhood Schools vs. Consolidation". There are benefits and concessions to each and there is not clear answer.

OPTIONS

Each of the three options presented should be considered carefully. All three have very different cost implications but all three also provide radically different outcome quality.

Option 1 - Do Nothing. This is not recommended because the current situation is not sustainable

Option 2 – Additions and Renovations over 5+ years. This is not recommended due to the high cost, difficulty in performing the work and low-quality return.

Option 3 – Additions and Renovations in One Year. This is worth considering in that it allows for a more efficient delivery of construction than Option 2 and is much less expensive due to efficiency of scale and lack of inflation. It however does not solve all the issues and has the greatest negative impact on education during construction.

Option 4 – New South Elementary School, Additions and Renovations Elsewhere. This solves the problem for the major parts of the community. It is relatively cost effective. It does not solve the problem at Cutler which is the school with the most difficult challenge in renovations.

Option 5 – New South Elementary School, Additions and Renovations at Mt Caesar to create a North Elementary School. This solves the problem for most of the community. It is relatively cost effective.

Option 6 – Consolidate onto One Site. This is not recommended for two reasons: The size and the loss of community schools. Consolidation would reduce operating costs but would put a transportation burden on many families in the district.

Option 7 – Consolidate Across Town Borders. This would create a North and South and possibly a third Elementary School that are not restricted to town lines. This could allow for locations that are dictated by demographics, not political boundaries.

End Report


	Number	Actual		Number	Estimate									
	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	5 year	3 year Wtd
Births	106	129	129	100	124	98	109	104	106	106	106	106	107	105
PK	51	60	70	60	74	101	94	83	95				93	91
K	134	137	114	138	122	142	136	126	134				132	132
1	124	119	130	112	130	128	128	128	131				129	130
2	133	111	138	118	121	130	134	133	121				128	127
3	130	134	127	127	113	118	134	129	133				125	132
4	139	144	147	110	120	100	109	124	123				115	121
5	146	139	138	139	104	112	109	113	126				113	119
6	151	143	138	123	139	108	107	106	117				115	112
Tot. Elem	1008	987	1002	927	923	939	951	942	980				118.856	120.313
			(Cohort	Surviva	l Ratios	3							
		2011	2012	2013	2014	2015	2016	2017	2018			5 year	3 year Wto	Simple
PK								0.83	0.76613					0.75
K		2.68627	1.9	1.97143	2.03333	1.91892	1.34653	1.34043	1.61446			1.650734	1.47846	1.33
1		0.88806	0.94891	0.98246	0.94203	1.04918	0.90141	0.94118	1.03968			0.974695	0.983802	1
2		0.89516	1.15966	0.90769	1.08036	1	1.04688	1.03906	0.94531			1.022321	0.99349	1
3		1.00752	1.14414	0.92029	0.95763	0.97521	1.03077	0.96269	1			0.985258	0.99269	1
4		1.10769	1.09701	0.86614	0.94488	0.88496	0.92373	0.92537	0.95349			0.926486	0.939157	1
5		1	0.95833	0.94558	0.94545	0.93333	1.09	1.0367	1.01613			1.004323	1.035297	1
6		0.97945	0.99281	0.8913	1	1.03846	0.95536	0.97248	1.0354			1.000339	1.001084	1
Avg.		0.9796	1.0501	0.9189	0.9784	0.9802	0.9914	0.9796	0.9983			0.98557	0.99092	1

Monadnock Regional School District Distric Wide Elementary Schools

Enrollment Projections

	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	5 Year
PK	95	75	83	79	81	81	81	81				Average Projection
K	134	157	124	137	130	134	134	134	134	0	0	
1	131	131	153	121	134	127	131	131	131	131	0	
2	121	134	134	156	124	137	130	134	134	134	134	
3	133	119	132	132	154	122	135	128	132	132	132	
4	123	123	110	122	122	143	113	125	119	122	122	
5	126	124	124	110	123	123	144	113	126	120	123	
6	117	126	124	124	110	123	123	144	113	126	120	
Tot. Elem	980	989	984	981	978	990	991	990	889	765	631	
	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	3 Year Weighted
PK	95	77	85	81	83	83	83	83				Average Projection
Κ	134	140	114	126	120	123	123	123	123	0	0	
1	131	132	138	112	124	118	121	121	121	121	0	
2	121	130	131	137	111	123	117	120	120	120	120	
3	133	120	129	130	136	110	122	116	119	119	119	
4	123	125	113	121	122	128	103	115	109	112	112	
5	126	127	129	117	125	126	133	107	119	113	116	
6	117	126	127	129	117	125	126	133	107	119	113	
Tot. Elem	980	977	966	953	938	936	928	918	818	704	580	
	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	Simple Projection
PK	95	74	82	78	79	79	79	79				
К	134	127	99	109	104	105	105	105	105	0	0	
1	131	134	127	99	109	104	105	105	105	105	0	
2	121	131	134	127	99	109	104	105	105	105	105	
3	133	121	131	134	127	99	109	104	105	105	105	
4	123	133	121	131	134	127	99	109	104	105	105	
5	126	123	133	121	131	134	127	99	109	104	105	
6	117	126	123	133	121	131	134	127	99	109	104	
Tot. Elem	980	969	950	932	904	888	862	833	732	633	524	

GRAPH A




Cutler Elementary School




View of main entrance



View of historic main entrance now exit only View is from driveway entrance. Note the current front entrance in alley to the left.



View of front lobby looking upstairs to principal's office. The lobby is open to the corridors of later wings and not fire rated nor secure.




Entrance to a special needs classroom that is not handicap accessible.



View of Library.

Note the column in the center of the room and the emergency exit to the outside towards the left.



View of corridor leading to original front entrance.

Note the steps in the foreground making this part of the building not handicap accessible. Also note the stairs on the right to the basement.




View of front lobby looking upstairs to principal's office. The lobby is open to the corridors of later wings and not fire rated nor secure.



View of corridor into portable classrooms and the exit.



View of s typical classroom.



View of gymnasium.



View of non-public entrance between portable classrooms.



View of narrow alley that busses must pass through.




Exterior with mold from past moisture problems.



View of the rear of the 3-story structure.

Note the fire escape that does not meet code.

Note also the courtyard between the building wings that extends to the front lobby.



KEY PLAN

CONSULTANTS




P: (603)731-7796 WWW.BARKERARCHITECTS.COM

MONADNOCK REGIONAL SCHOOL DISTRICT ELEMENTARY SCHOOLS ASSESSMENT STUDY CUTLER ELEMENTARY SCHOOL EXISTING SITE PLAN


DATE: OCTOBER. 31, 2019 SCALE: AS NOTED





KEY PLAN

SECOND FLOOR PLAN



SCALE

LEGEND

EXIT WITH OCCUPANT LOAD (ABOVE) CAPACITY (BELOW)

REQUIRED FIRE RATED AREA

LONGEST TRAVEL DISTANCE TO EXIT

COMMON PATH OF TRAVEL TO 2 MEANS OF EGRESS

ASSEMBLY DIAGONAL DISTANCE

ASSEMBLY EXIT REMOTENESS

 $^{\rm 371} \begin{array}{c} {\rm OCCUPANT\ LOAD\ AND} \\ {\rm EGRESS\ DIRECTION} \end{array}$


CONSULTANTS



8 KEARSARGE STREET CONCORD, NH 03301 P: (603)731-7796 WWW.BARKERARCHITECTS.COM

MONADNOCK REGIONAL SCHOOL DISTRICT ELEMENTARY SCHOOLS ASSESSMENT STUDY CUTLER ELEMENTARY SCHOOL EXISTING CONDITIONS PLANS

DATE: OCTOBER. 31, 2019 SCALE: AS NOTED



6 GRADE
CLASSICOM
G95 SF

6 GRADE
CLASSICOM
T322
715 SF

SECOND FLOOR PLAN

KEY PLAN CONSULTANTS P: (603)731-7796 WWW.BARKERARCHITECTS.COM MONADNOCK REGIONAL SCHOOL DISTRICT ELEMENTARY SCHOOLS ASSESSMENT STUDY CUTLER ELEMENTARY SCHOOL EXISTING CONDITIONS PLANS DATE: OCTOBER. 31, 2019 SCALE: AS NOTED

SCALE

LEGEND

CORRIDORS

STAIRS

TOILETS

CORE AREAS

SPECIALS

CLASSROOMS



BASIC INFORMATION					
Location:	AREA	Building A	Building B	Building C	Total
31 S. Winchester St.	1st Floor	4982			4982
Swanzey, NH 03446	2nd Floor	4982	20090	2101	27173
	3rd Floor	2498			2498
	T-4-1	40400	20000	0404	24052
	Total	12462	20090	2101	34653
	Stories	3	1	1	
	Height	35	25	15	
	Footprint	9964	40180	4202	
	Perimeter	321.5	925	207	
	Const. Class	5b	3b	5b	
	Building Type	SM	S1	S1	
	Frontage min. 20'	268.5	624	103	
	Frontage min. 30'	268.5	584	103	
	Weighted Width	30.00	29.36	30.00	

APPLICABLE CODES

NEW HAMPSHIRE STATE BUILDING CODE

2015 EDITION INTERNATIONAL BUILDING CODE (IBC)

2015 EDITION INTERNATIONAL ENERGY CONSERVATION CODE (IECC)

2015 EDITION INTERNATIONAL EXISTING BUILDING CODE (IEBC)

2015 EDITION INTERNATIONAL MECHANICAL CODE (IMC)
2015 EDITION INTERNATIONAL PLUMBING CODE (IPC)
2017 EDITION NATIONAL ELECTRICAL CODE (NEC)

NEW HAMPSHIRE SAF-C 6000 BUILDING SAFETY CODE

2015 EDITION NFPA 1 UNIFORM FIRE CODE 2015 EDITION NFPA 101 LIFE SAFETY CODE

NEW HAMPSHIRE BARRIER FREE DESIGN CODE

2010 EDITION ADA STANDARDS FOR ACCESSIBLE DESIGN

NH DEPT OF EDUCATION STANDARDS

Approval of plan set by the State Fire Marshal required. Designs to meet the following codes:

State of NH Fire Code

2015 NFPA 101 - Life Safety Code

NH Code for Barrier Free Design and 2010 ADAAG when applicable

ANSI S12.60 Acoustical Performance Criteria, Design Requirements and Guidelines for Schools

Grade Level Elementary (Elementary, Middle, High)

Design Capacity: 275 sudents
Core Capacity: 320 sudents

Max. Building Size: Max. Construction:

Minimum Size Standards

	Minimum Value	Preferred Total
Classrooms	36 s.f. per student	900 s.f.
Kindergartens	50 s.f. per student	1000 s.f.
Library	40 s.f. per student	1800 s.f.
Phys. Ed.	110 s.f. per student	700 s.f.
Office	60 s.f. per person	1200 s.f.
Nurse	1 cot per 200 stud.	300 s.f.

DIIII	DINIO	DATA
DUIL	-טוועט	DATA

Use and Occupancy Classification

Primary Use

Accessory Use

Educational Assembly Business Storage

No

Area by Use

	Building A	Building B	Building C	Total
	7754	7189	1668	16611
		5157		5157
	180	1757		1937
		540		540
	4528	5447	433	10408
Total	12462	20090	2101	34653

Mixed Use

Construction Type

Sprinklers Yes

NFPA 13 30.3.5.2

Fire Alarm System Yes 30.3.4.1.1

Refer to Code Plan for Use Area Locations.

OCCUPANT LOAD

Classification

7.3.1.2

		Building A	Building B	Building C	Total
Classrooms	20sf/person	303	367	84	754
Library (Reading)	50sf/person net	28			28
Library (Stacks)	100sf/person	12			12
Assembly	15sf/person net		737		737
Storage & Mech.	300sf/ person				0
Kitchen	200sf/ person		6		6
Locker room	50sf/person				0
Business	100sf/person	2	11		13
	Total	345	1121	84	1550

Refer to Code Plan for occupancy load per room.

MEANS OF EGRESS

	. 50	New Educational	Exist Educational	Provided	
Location of PK, K and 1st Grade	LED	14.2.1.2	15.2.1.2	COMPLIANT	
Corridor Width	6'-0"	14.2.3.2	15.2.3.2	COMPLIANT	
Number of Exits	2	14.2.4	15.2.4	NON-COMPIANT	Building A
Rooms Over 1000 sf	2	14.2.5.4	15.2.5.4	COMPLIANT	
Assembly over 500	3	7.4.1.2	7.4.1.2	COMPLIANT	
Dead End Corridor	50'	14.2.5.2	15.2.5.2	COMPLIANT	
Common Path of Travel	100'	14.2.5.3.2	15.2.5.3.2	COMPLIANT	
Travel Distance to Exit	200'	14.2.6.2	15.2.6.2	COMPLIANT	
Windows for Rescue	No	14.2.11.1.2(2)	15.2.11.1.2(2)	SPRINK. EXCEPT.	

Refer to Code Plan for Egress, Exit Access, Maximum Travel , Maximum Common Path and Maximum Dead End Corridor.

PROTECTION	

	nours	
Exit Stairs	1	
Shafts	1	
Horizontal Assemblies	1	
Exit Access Corridors	S	14.3.6(2)
Smoke Compatments	N/A	14.3.7.2(2)

Hazardous Rooms Boiler Room Storage Room Janitor Closet

Hours **SPRINKLER** 15.3.2.1 **SPRINKLER** 15.3.2.1 SPRINKLER 15.3.2.1

See Code Plan for locations of rated partitions.

INTERIOR FINISHES

Allowable Finishes	Class
Exits and Exit Passageways	Α
Exit Access Corridors	В
Other Areas	С

BUILDING DATA					
Use and Occupar	ncy Classification				
Building A	Primary Use	E		Number of Stories	3
Fire Area #1	Accessory Use	A		Height	35 LF
i ile Alea # i	Accessory Use	В		1st Floor	4982 SF
	Accessory Ose	Б	Area	2nd Floor	4982 SF
	Mixed Use	No	₹	3rd Floor	2498
	Construction Type	5b		Footprint	4982 LF
	Sprinklers	Yes		Perimeter	321.5 LF
	Building Type	SM		Frontage	268.5 LF
	Januarig Type	J		Weighted Width	30.00 LF
This Fire Ar	ea does not	Meet Code for Heigh	This Fire Area	is	Within Allowable Area
Building B	Primary Use	A-3		Number of Stories	1
Fire Area #2	Accessory Use	E		Height	25 LF
	, .		_	1st Floor	0 SF
			Area	2nd Floor	20090
	Mixed Use	No	₹	3rd Floor	0
	Construction Type	3b		Footprint	20090 LF
	Sprinklers	Yes		Perimeter	925 LF
	Building Type	S1		Frontage	624 LF
	3 -71-			Weighted Width	29.36 LF
This Fire Ar	ea does	Meet Code for Heigh	This Fire Area	is	Within Allowable Area
Building C	Primary Use	Е		Number of Stories	1
Fire Area #3	Accessory Use	_	Area	Height	15 LF
5 / 11 50 17 6	. 10000001 y 000		/ ilea	1st Floor	0 SF
				2nd Floor	2101
	Mixed Use	No		3rd Floor	0
	Construction Type	5b		Footprint	2101 LF
	• • • • • • • • • • • • • • • • • • • •	Yes		Perimeter	2101 LF 207 LF
	Sprinklers	Yes S1			
	Building Type	31		Frontage Weighted Width	103 LF 30.00 LF
This Fire Ar	ea does	Meet Code for Heigh	This Fire Area	is	Within Allowable Area
		Fire Area #1	Fire Area #2	Fire Area #3	
Separated Uses		0	0	0	
Fire Alarm Syster	n	Yes	Yes	Yes	
Existing Building		. 55	. 30	. 00	1, 2, 3
CONSTRUCTION	CLASSIFICATION				
Table 601	-	Fire Area #1	Fire Area #2	Fire Area #3	
'		5b	3b	5b	
Element		Rating	Rating	Rating	
Primary Structura	al Frame	0	0	0	
Bearing Walls	Exterior	0	2	0	
_ caing wais	Interior	0	0	0	
Non Bearing	Exterior	0	2	0	
	Interior	0	0	0	
Floors	intolioi	0	0	0	
Roofs		0	0	0	
See Code Plan fo	r locations of rated par	titions.			
PROTECTION					
	Hours		Incidental Rooms	Hours	
Firewalls	2	Table 706.4	Table 508.2.5	riours	
Fire Barriers	1	Table 707.3.9	Boiler Room	1	
Shafts	1	708.4	Sprinkler Room	1	
Fire Partitions	1	709.4	Opinico (Cooli		

See Code Plan for locations of rated partitions.

Smoke

Fire Partitions

Horiz. Assemblies

Exit Stairs

Exit Access

709.1

708

712

1018.1

INTERIOR FINISHES

Allowable Finishes Table 803.9	Fire Area #1	Fire Area #2	Fire Area #3
Exits and Exit Passageways	В	В	В
Exit Access Corridors	С	С	С
Other Areas	С	С	С

OCCUPANT LOAD

Refer to Code Floor Plan for occupancy load per room.			1004.1.1			
Classification			Building A	Building B	Building C	Total
	Educational					794
	Classrooms	20sf/person gross	303	367	84	
	Library (Reading)	50sf/person net	28			
	Library (Stacks)	100sf/person gross	12			
	Assembly	15sf/person net		737		737
	Business					19
	Kitchen	200sf/ person gross		6		
	Offices	100sf/person gross	2	11		
		TOTAL	345	1121	84	1550

Refer to Code Plan for Egress, Exit Access, Maximum Travel , Maximum Common Path and Maximum Dead End Corridor.

MEANS OF EGRESS

		Required		Provided/Worst Case
Number of Exits	Under 49 occ.	1	1006.2.1	1
	Over 49 under 500	2	1006.2.1	2
	Over 500 under 1000	3	1006.2.1.1	3
Common Path of Travel		75	Table 1006.2.1	46
Exit Access Travel D	Distance	250	Table 1017.2	141
Dead End Corridor		50	1020.4(2)	16

(if shared)

PLUMBING REQUIREMENTS

	Classification	Required Water Closets	2902.1 Lavatories	Showers	Drinking Fountains	Service Sink
Primary Use	E	16	16	-	8	1
Accessory Use	Α				2	1
	Men	3	2	-		
	Women	6	2	-		
	В	1	1	-	1	1

Primary Use E
Accessory Use A
Men
Women
B

Provided Water Closets	Lavatories	Showers	Drinking Fountains	Service Sink
17	10	1	3 0	1 1
2	1	-		
2	1	-		
4	4	-	0	1
COMPLIANT	NON-COMPLIANT	COMPLIANT	NON-COMPLIANT	COMPLIANT

Uses are not subject to simultaneous occpancy so therefore fixtures can be shared between uses. This does require that toilet facilities in other parts of the building from the gymnasium be open when the gym is in use.

ENERGY CODE

Using Prescriptive Method for compliance

		Required	Provided	
Roof	(Attic and Other)	R-30ci	COMPLIANT	Only in 1996 addition. NON-COMPLIANT elsewhere
Walls	(Wood Framed)	R-11.4ci	COMPLIANT	Only in 1996 addition. NON-COMPLIANT elsewhere
Bewlow Grade		R-7.5ci	COMPLIANT	Only in 1996 addition. NON-COMPLIANT elsewhere
Heated Slabs		R-15 for 24"	N/A	
Doors		U-0.70	NON-COMPLIANT	Unknown
Windows		U-0.35	NON-COMPLIANT	Unknown

Cutler Elementary School Existing Building Needs

 Basement
 1st Floor
 2nd Floor
 Total

 Area
 4,982
 27,284
 2,498
 34,764

 Perimeter
 1,290

Cat	ltem	Existing Descriptions	Corrective Measure		High	М	Cost / edium	Priority Low	Future
	1 Minimum Size Lot 2 Water and Septic	Town municipal water and sewer.							
Site	3 Bus/Car Separation 4 Parking/Drives 5 Playground/Playfields	The bus and car separation is very awkward. Driveway too close to building creating a hazard.	Reconfigure drive to create a safe bus loop. Install speed bumps or restripe to shift the traffic pattern.	\$	1,500				
	6 Site Features 7 Grading/Drainage	Stair at northwest corner in disrepair. No significant problems.	Replace stairs to be in compliance with current codes.	\$	12,000				
	8 Oil, Propane Tank Age/Condition 9 Roof Condition	Current fuel source is oil.	Change oil tank to propane.	ć	FO 000	\$	40,000		
	9 ROOT CONDITION 10 Wall Condition (insulation and moisture protection)	Evidence of some minor leaking. Walls have minimal insulation. The '90's wing is showing signs of moisture issues with mold on the split-faced block.	Some work has been done. Clean mold and seal block.	\$	50,000	\$	10,000		
Envelope	11 Door Condition (energy efficiency and operation)	There is a gap at stairway exit from Literary Room. The gym double doors are energy inefficient and corroded.	Replace literary room door. Replace gym door.	\$	5,000	\$	5,000		
En	12 Window Condition (energy efficiency and operation)	Sealant around 1950s addition are failing. Paint around glass block is in poor condition. Older windows are past their usful life and are not energy	Seal around 1950s addition windows. Paint wood trim. Replace windows in 1950s and 1970's sections.	\$	19,000	\$	300,000		
	13 Foundation Condition (insulation and moisture protection)	efficient.							
	14 K-2 location based on LED								
	15 Panic devices 16 Stair Details (Rise/Run, Railings)	Handicap stair lift interferes with stair egress.							
	17 Areas of Refuge 18 Capacity of Means of Egress	Gymnasium doors do not meet code for width.	Install additional door leaf.	\$	5,000				
	19 Corridor Width 20 Number of Exits	The 3-story section does not provide two legitimate	Rearrange to create two remote means of egress, or	????					
	21 Dead-end Corridors 22 Exits through Intervening Rooms	means of egress from every floor.	cease using the top floor.						
Safel	23 Door Arrangement								
	24 Travel Distance25 Means of Escape26 Protection of Vertical Openings	Existing stair has breaches in the fire rating.	Remove obstructions, install new fire rated doors and	\$	10,000				
	27 Protection of Hazards 28 Protection of Corridors	Some doors to classrooms do not resist the passage	seal unprotected openings. Replace damaged classroom doors with smoke doors.	\$	4,000				
	29 Smoke Compartments 30 Fire Alarm, Emergency lights and Exit lighting	of smoke. Fire alarm system recently replaced.							
	31 Furnishings, Decorations and Personal Effects in the Corridor								
Code	32 Height and Area Limitations33 Construction Classification								
Building Code	34 Fire Rated Construction 35 Sprinklers	The building has an automatic sprinkler system.							
Bu	36 Fire Protection 37 Snow Load Capacity	g							
tural	38 Wall Condition (seismic capacity, cracks or deflection)								
Structural	39 Floor Load Capacity								
	40 Foundation Condition (cracks or rot) 41 Parking 42 Building Access								
bility	43 Accessible Route 44 Clearances	The second floor of the 1950s addition is not accessible.	Extend the stair lift to the second floor.			\$	25,000		
Accessibility	45 Door Hardware 46 Stair Details								
	47 Toilet Facilities 48 Signage	Not all toilet rooms are accessible.	Upgrade toilet rooms to make all comply.			\$	75,000		
	49 Elevator 50 Ventilation	??? Most classrooms have older unit ventilators. The	??? Replace ventilation system with all new.	\$	371,000	\$	340,000		
ental	51 Thermal Control	system is archaic and has no cooling. Control system non-extant.	install digital control system.	*	371,000		150,000		
Indoor Environmental Quality	52 Moisture / Mold 53 Lighting Quality 54 Acoustics	Control system non-extant.	ilistali uigitai controi systeili.			ş	130,000		
	55 Sanitation 56 Boiler Condition and Distribution	Chimney showing signs of creosote build-up. Boilers		\$	1,500	\$	175,000		
	57 Water Supply 58 Plumbing / Fixture Count	are reaching their expected life. Plumbing fixtures are archaic.	new gas fire boilers and propane tanks. Replace with new water-efficient fixtures.			\$	44,000		
Services	59 Kitchen Equipment60 Main Electrical Service		replace with new water-enforch hazules.			Ţ	4 4 ,000		
Build. S	61 Generator 62 Power Distribution 63 Lighting Efficiency	No generator. Outlets are aging and quantity low for technology. Lighting is archaic, energy inefficient and in poor	Upgrade outlets. Replace lights with LED fixtures.			\$	34,000	\$ 150,000	
	64 Site lighting	condition. Limited site lighting.	Add LED site lights for safety and security.					\$ 20,000	
	65 Roof Drains 66 Phone, Intercom, Security	Existing system is relatively new but not integrated.							
	67 Ceilings	Most ceilings in reasonable condition. The ceilings of the original building are archaic and have some damage.	Replace ceilings in original building.	\$	10,000	\$	70,000		
rior	68 Walls 69 Floors	VCT in 1970's corridor in poor condition.	Replace VCT in 1970s corridor.					\$ 40,000	
_	70 Doors 71 Cabinetry	Many doors are showing signs of wear.	Replace doors in original through 1970's wings.			\$	20,000		
	72 Fixed Equipment 73 Visual Display Boards	Some rooms have been undated to new standard of	Update remainder of classrooms to district standards.			\$	18,000		
	74 Lock-down of public areas	boards and technology. The gymnasium can be locked down from remainder				Ÿ	10,000		
	·	of school.	Add a vestibula for					6 400.000	
ity and	75 Secure Visitor Check-in 76 Technology 77 Physical Hazards	There is no locked vestibule for security. School has cameras.	Add a vestibule for security and energy efficiency.					\$ 100,000	
Secur	78 Hazardous Materials 79 Visibility	visual connection to driveways and parking is limited.							
snoə	80 81								
scela	82 83 84								
_	85								
				\$	589,000	\$ 1	,306,000	\$ 310,000	\$ -

TTG Study Recommendations Changes to TTG Study Barker Architects Recommendations Total Renovations \$ 2,205,000

 Cost Per S.F.
 Value of Existing
 Renovation Minimum
 Maximum

 State Funding Thresholds
 178
 \$ 6,187,992
 \$ 1,546,998
 \$ 3,712,795

Cutler Elementary School

Curriculum Worksheet

Design Capacity	275
Core Capacity (Theoretical Max.)	370
Periods Per Day	6
Number of grades (include K)	4

Sub	<u>ject</u>	Avg. Students/ grade	Avg. Size		Max. Students/ grade	Max Size	Teaching Stations
3 4 5 6	Grade Classrooms Grade Classrooms Grade Classrooms Grade Classrooms	69 69 69 69	20 20 22 22		88 88 96 96	22 22 24 24	4.0 4.0 4.0 4.0 16.0
		% enrolled	Total	Max Size	Me	eetings / Week	Required Stations
Spe	cial Ed. /Specialists (2) Resource OT / PT Speech Reading	20%	74	6		10	5.0 5.0
Reg	jular Ed Special Rooms Science						
	Art	100%	370	25		1 1	1.0
	Music Phys. Ed. (3)	100% 100%	370 370	25 25		2	0.0 1.0

¹ Kindergarten is full day.

Table E

Barker Architects, PLLC

11/17/2019

Actual Special Ed and Specialists required spaces varies considerably from school to school.

Secialists include regular ed small group instruction. Above calculation is solely for computing purposes. Required spaces should be base on actual programs.

³ Gymnasium to be designed for 2 teachings stations simultaneously.

Cutler Elementary School

Sq. Ft. / Student (Design Cap.)

Sq. Ft. / Student (Core Cap.)

Space Needs Worksheet

Design Capacity 275 Core Capacity 370

	ELEMENT	[DESIG	V	E	XISTIN	G		COMMENT
		#	SIZE	TOTAL	#	SIZE	TOTAL		
EDUCATIONAL SPACES	Classrooms Art	16	900	14400	16	796 830	12731 830	88% 83%	There is a wide range of classroom sizes. Some are well below DOE recommendations. Music and Art rooms combined in some schools.
ΞĐΩ	Music	0	1000	0	4	400	4007	4440/	
ш	Special Ed. /Specialists	5	360	1800	4	499	1997	111%	
	Phys Ed			5600			5527	99%	
	Food Service Caf. / Multi-Purpose Rm								The gym also surves as the cafeteria and assembly space.
	Kitchen			863			539	62%	space.
SES	Assembly			1000			0	0%	
PA	Library			1800			1115	62%	
CORE SPACES	Stacks	1	1400						
SOF	Computer	1	400						
Ū	Offices			1480			1129	76%	
	Admin./Guid.		900						
	Faculty / Work		280						
	Nurse		300						
	Subtotal			27943			23868		
	MiscCirc, Mech, Toilets, Janitor Storage		40%	11177		46%	10896		Due to functional obsolescence there is a high level of non-program space.
	Totals			39121			34764		

142

106

Table F

Barker Architects, PLLC 11/17/2019


126

94

Emerson Elementary School



View of main entrance.



View of main lobby.

Note the exposed heating pipes.


The entrance to the main office is to the right.



View of the library. Note the columns.



Basement corridor that is too narrow for code.




An unprotected vent into the corridor.

Note the residential fans.

Corridors need to resist the passage of smoke.



A classroom doorway that is not handicap accessible due to lack of pull-side clearance.



View of unprotected stair to basement.



Archaic fin-tube heating element with foam duct-taped to it for protection.



Typical classroom.



View of Gymnasium.



BEVENINE

KEY PLAN

.....




EARSARGE STREET CONCORD, NH 03301

MENTARY SCHOOLS ASSESSMENT STUDY

DATE: OCTOBER 31, 2019 SCALE: AS NOTED

EX1



KEY PLAN

CONSULTANTS

CODE NOTES PRESCHOOL THRU 1ST GRADE RESTRICTED TO LED MINIMUM CORRIDOR WIDTH OF 6'-0" REQUIRED TWO SEPARATE EXITS REQUIRED DEAD-END CORRIDOR NOT TO EXCEED 50'-0" COMMON PATH NOT TO EXCEED 100'-0" ROOMS LARGER THAN 1000 SF REQUIRE 2 EXITS DOORS CANNOT INTERFERE WITH CORRIDOR TRAVEL TRAVEL DISTANCE TO EXIT CANNOT EXCEED 200'-0" CORRIDORS ARE REQUIRED TO BE SMOKE RESISTANT EXITS ARE REQUIRED TO BE FIRE RATED ROOMS ARE REQUIRED TO BE FIRE RATED MULTIPLE EXITS ARE REQUIRED TO BE REMOTE OCCUPANT LOAD CANNOT EXCEED EGRESS WIDTH ADA REQUIRES ACCESSIBLE ROUTE ADA REQUIRES ACCESSIBLE FIXTURES

Barker

8 KEARSARGE STREET CONCORD, NH 03301 P: (603)731-7796 WWW.BARKERARCHITECTS.COM


> MONADNOCK REGIONAL SCHOOL DISTRICT ELEMENTARY SCHOOLS ASSESSMENT STUDY

EMERSON ELEMENTARY SCHOOL EXISTING CONDITIONS PLANS

LEGEND


OCCUPANT LOAD AND EGRESS DIRECTION

SCALE









DIAGONAL DISTANCE

DATE: OCTOBER 31, 2019
SCALE: AS NOTED

EX2



BASIC INFORMATION						
Location:	AREA	Building A	Building B	Building C	Total	
31 S. Winchester St.	1st Floor	3314				3314
Swanzey, NH 03446	2nd Floor	3494	26044			29538
	3rd Floor					0
	Total	6808	26044			32852
	Total	0000	20044			32032
	Stories	2	1			
	Height	25	30			
	Footprint	3494	26044			
	Perimeter	292	1190			
	Const. Class	5b	5b			
	Building Type	SM	S1			
	Frontage min. 20'	260	1158			
	Frontage min. 30'	260	1158			
	Weighted Width	30	30			

APPLICABLE CODES

NEW HAMPSHIRE STATE BUILDING CODE

2015 EDITION INTERNATIONAL BUILDING CODE (IBC)

2015 EDITION INTERNATIONAL ENERGY CONSERVATION CODE (IECC)

2015 EDITION INTERNATIONAL EXISTING BUILDING CODE (IEBC)

2015 EDITION INTERNATIONAL MECHANICAL CODE (IMC)
2015 EDITION INTERNATIONAL PLUMBING CODE (IPC)
2017 EDITION NATIONAL ELECTRICAL CODE (NEC)

NEW HAMPSHIRE SAF-C 6000 BUILDING SAFETY CODE

2015 EDITION NFPA 1 UNIFORM FIRE CODE 2015 EDITION NFPA 101 LIFE SAFETY CODE

NEW HAMPSHIRE BARRIER FREE DESIGN CODE

2010 EDITION ADA STANDARDS FOR ACCESSIBLE DESIGN

NH DEPT OF EDUCATION STANDARDS

Approval of plan set by the State Fire Marshal required. Designs to meet the following codes:

State of NH Fire Code

2015 NFPA 101 - Life Safety Code

NH Code for Barrier Free Design and 2010 ADAAG when applicable

ANSI S12.60 Acoustical Performance Criteria, Design Requirements and Guidelines for Schools

Grade Level Elementary (Elementary, Middle, High)

Design Capacity: 200 students Core Capacity: 250 students

Max. Building Size: Max. Construction:

Minimum Size Standards

	Minimum Value	Preferred Total
Classrooms	36 s.f. per student	900 s.f.
Kindergartens	50 s.f. per student	1000 s.f.
Library	40 s.f. per student	1800 s.f.
Phys. Ed.	110 s.f. per student	700 s.f.
Office	60 s.f. per person	1200 s.f.
Nurse	1 cot per 200 stud.	300 s.f.

Total

620

RΙ	111	7	IN I)	7	^ 7	- ^
м	"	1)	IIV.		. ,,	41	A

Use and Occupancy Classification

Primary Use Accessory Use Educational

Assembly Business Storage Misc.

No

Area by Use

	Building A	Building B	Total
	11167	12636	23803
	1115	5157	6272
	180	1757	1937
		540	540
Total	12462	20090	32552

Mixed Use

Construction Type

Sprinklers Fire Alarm System

NFPA 13 30.3.5.2 Yes Yes 30.3.4.1.1

Refer to Code Plan for Use Area Locations.

OCCUPANT LOAD

Classification 7.3.1.2

> Building A Classrooms 20sf/person 70 Library (Reading) 50sf/person net 100sf/person Library (Stacks) 15sf/person net Assembly Storage & Mech. 300sf/ person 200sf/ person Kitchen 50sf/person Locker room Business 100sf/person

10 10 5 5 765 765 0 6 6 0 18 4 22

Building B

550

Total 103 1325 1428

Refer to Code Plan for occupancy load per room.

MEANS OF EGRESS

		New Educational	Exist Educational	Provided	
Location of PK, K and 1st Grade	LED	14.2.1.2	15.2.1.2	COMPLIANT	
Corridor Width	6'-0"	14.2.3.2	15.2.3.2	COMPLIANT	
Number of Exits	2	14.2.4	15.2.4	NON-COMPIANT	Building A
Rooms Over 1000 sf	2	14.2.5.4	15.2.5.4	COMPLIANT	
Assembly over 500	3	7.4.1.2	7.4.1.2	COMPLIANT	
Dead End Corridor	50'	14.2.5.2	15.2.5.2	COMPLIANT	
Common Path of Travel	100'	14.2.5.3.2	15.2.5.3.2	COMPLIANT	
Travel Distance to Exit	200'	14.2.6.2	15.2.6.2	COMPLIANT	
Windows for Rescue	No	14.2.11.1.2(2)	15.2.11.1.2(2)	SPRINK. EXCEPT.	

Refer to Code Plan for Egress, Exit Access, Maximum Travel , Maximum Common Path and Maximum Dead End Corridor.

PROTECTION

Hours **Exit Stairs** 1 Shafts Horizontal Assemblies 1 **Exit Access Corridors** S 14.3.6(2) **Smoke Compatments** N/A 14.3.7.2(2)

Hazardous Rooms Boiler Room Storage Room Janitor Closet

Hours SPRINKLER 15.3.2.1 **SPRINKLER** 15.3.2.1 **SPRINKLER** 15.3.2.1

See Code Plan for locations of rated partitions.

INTERIOR FINISHES

Allowable Finishes Class Exits and Exit Passageways Α Exit Access Corridors В Other Areas C

Use and Occupand	v Classification				
ose and Occupand Building A	Primary Use	Е		Number of Stories	2
•					
Fire Area #1	Accessory Use	A		Height	24.00 LF
	Accessory Use	В	a	1st Floor	3314 SF
			Area	2nd Floor	3494 SF
	Mixed Use	No	*	3rd Floor	0
	Construction Type	5b		Footprint	3494 LF
	Sprinklers	Yes		Perimeter	1120 LF
	Building Type	SM		Frontage	1090 LF
	building Type	Sivi		•	30 LF
				Weighted Width	30 LF
This Fire Area	does	Meet Code for Heigh	This Fire Area	is	Within Allowable Area
Building B	Primary Use	A-3		Number of Stories	1
Fire Area #2	Accessory Use	E		Height	30.00 LF
		В	m	1st Floor	0 SF
			Area	2nd Floor	26044
	Mixed Use	No	₹	3rd Floor	0
	Construction Type	5b		Footprint	26044 LF
	Sprinklers	Yes		Perimeter	1190 LF
	Building Type	S1		Frontage	1158 LF
				Weighted Width	30 LF
This Eiro Area	dasa	Meet Code for Heigh	This Fire Area		Within Allowable Area
This Fire Area	a does	Inter Code for Heigh	This Fire Area	is	Within Allowable Area
Building C	Primary Use			Number of Stories	0
Fire Area #3	Accessory Use		Area	Height	0 LF
1 110 7 11 00 770	7 lococool y Coo		7 11 00	1st Floor	0 SF
				2nd Floor	0
	Mixed Use			3rd Floor	0
	Construction Type			Footprint	0 LF
	Sprinklers			Perimeter	0 LF
	•				
	Building Type			Frontage	0 LF
				Weighted Width	0 LF
This Fire Area	a	Meet Code for Heigh	This Fire Area		Within Allowable Area
		Fire Area #1		F: A #0	
		i ii c Ai ca # i	Fire Area #2	Fire Area #3	
Senarated Hees					
•		0	0	0	
•					
Fire Alarm System	teration Level	0	0	0	1, 2, 3
Fire Alarm System Existing Building Al		0	0	0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C		0	0	0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C		0 Yes Fire Area #1	0 Yes Fire Area #2	0 Yes Fire Area #3	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601		0 Yes Fire Area #1 5b	0 Yes Fire Area #2 5b	0 Yes Fire Area #3 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element	LASSIFICATION	0 Yes Fire Area #1 5b Rating	0 Yes Fire Area #2 5b Rating	0 Yes Fire Area #3 0 Rating	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural	LASSIFICATION Frame	0 Yes Fire Area #1 5b Rating 0	0 Yes Fire Area #2 5b Rating 0	0 Yes Fire Area #3 0 Rating 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural	LASSIFICATION Frame Exterior	0 Yes Fire Area #1 5b Rating	0 Yes Fire Area #2 5b Rating	0 Yes Fire Area #3 0 Rating	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural	LASSIFICATION Frame	0 Yes Fire Area #1 5b Rating 0	0 Yes Fire Area #2 5b Rating 0	0 Yes Fire Area #3 0 Rating 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls	LASSIFICATION Frame Exterior	O Yes Fire Area #1 5b Rating 0 0	O Yes Fire Area #2 5b Rating 0 0	O Yes Fire Area #3 O Rating O O	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls	LASSIFICATION Frame Exterior Interior Exterior	Fire Area #1 5b Rating 0 0 0	O Yes Fire Area #2 5b Rating 0 0 0	Fire Area #3 0 Rating 0 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing	LASSIFICATION Frame Exterior Interior	Fire Area #1 5b Rating 0 0 0 0	O Yes Fire Area #2 5b Rating 0 0 0 0	Fire Area #3 0 Rating 0 0 0 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing	LASSIFICATION Frame Exterior Interior Exterior	Fire Area #1 5b Rating 0 0 0 0 0	0 Yes Fire Area #2 5b Rating 0 0 0 0	0 Yes Fire Area #3 0 Rating 0 0 0 0 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing	LASSIFICATION Frame Exterior Interior Exterior	Fire Area #1 5b Rating 0 0 0 0	O Yes Fire Area #2 5b Rating 0 0 0 0	Fire Area #3 0 Rating 0 0 0 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing Floors Roofs	LASSIFICATION Frame Exterior Interior Exterior	0 Yes Fire Area #1 5b Rating 0 0 0 0 0 0	0 Yes Fire Area #2 5b Rating 0 0 0 0	0 Yes Fire Area #3 0 Rating 0 0 0 0 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing Floors Roofs See Code Plan for	Frame Exterior Interior Exterior Interior	0 Yes Fire Area #1 5b Rating 0 0 0 0 0 0	0 Yes Fire Area #2 5b Rating 0 0 0 0	0 Yes Fire Area #3 0 Rating 0 0 0 0 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing Floors Roofs See Code Plan for	Frame Exterior Interior Exterior Interior Interior	0 Yes Fire Area #1 5b Rating 0 0 0 0 0 0	Fire Area #2 5b Rating 0 0 0 0 0 0	Fire Area #3 0 Rating 0 0 0 0 0 0 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing Floors Roofs See Code Plan for	Exterior Interior Exterior Interior Interior Interior Interior Interior Interior	Fire Area #1 5b Rating 0 0 0 0 0 0 titions.	O Yes Fire Area #2 5b Rating 0 0 0 0 0 0 Incidental Rooms	0 Yes Fire Area #3 0 Rating 0 0 0 0 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing Floors Roofs See Code Plan for I PROTECTION	LASSIFICATION Frame Exterior Interior Exterior Interior Interior Interior Interior Interior	0 Yes Fire Area #1 5b Rating 0 0 0 0 0 titions.	Fire Area #2 5b Rating 0 0 0 0 0 0 0 Incidental Rooms Table 508.2.5	Fire Area #3 0 Rating 0 0 0 0 0 0 Hours	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing Floors Roofs See Code Plan for I PROTECTION	Exterior Interior Exterior Interior Interior Interior Interior Interior Interior	Fire Area #1 5b Rating 0 0 0 0 0 0 titions.	O Yes Fire Area #2 5b Rating 0 0 0 0 0 0 Incidental Rooms	Fire Area #3 0 Rating 0 0 0 0 0 0 0	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing Floors Roofs See Code Plan for I PROTECTION Firewalls Fire Barriers	LASSIFICATION Frame Exterior Interior Exterior Interior Interior Interior Interior Interior	0 Yes Fire Area #1 5b Rating 0 0 0 0 0 titions.	Fire Area #2 5b Rating 0 0 0 0 0 0 0 Incidental Rooms Table 508.2.5	Fire Area #3 0 Rating 0 0 0 0 0 0 Hours	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing Floors Roofs See Code Plan for I PROTECTION Firewalls Fire Barriers Shafts	Frame Exterior Interior Exterior Interior	0 Yes Fire Area #1 5b Rating 0 0 0 0 0 titions.	Fire Area #2 5b Rating 0 0 0 0 0 0 0 Incidental Rooms Table 508.2.5 Boiler Room	Fire Area #3 0 Rating 0 0 0 0 0 Hours	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing Floors Roofs See Code Plan for I PROTECTION Firewalls Fire Barriers Shafts Fire Partitions	Frame Exterior Interior Exterior Interior	0 Yes Fire Area #1 5b Rating 0 0 0 0 0 titions.	Fire Area #2 5b Rating 0 0 0 0 0 0 0 Incidental Rooms Table 508.2.5 Boiler Room	Fire Area #3 0 Rating 0 0 0 0 0 Hours	1, 2, 3
Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing Floors Roofs See Code Plan for I PROTECTION Firewalls Fire Barriers Shafts Fire Partitions Exit Stairs	Frame Exterior Interior Exterior Interior	0 Yes Fire Area #1 5b Rating 0 0 0 0 0 0 titions.	Fire Area #2 5b Rating 0 0 0 0 0 0 0 Incidental Rooms Table 508.2.5 Boiler Room	Fire Area #3 0 Rating 0 0 0 0 0 Hours	1, 2, 3
Separated Uses Fire Alarm System Existing Building Al CONSTRUCTION C Table 601 Element Primary Structural Bearing Walls Non Bearing Floors Roofs See Code Plan for I PROTECTION Firewalls Fire Barriers Shafts Fire Partitions Exit Stairs Horiz. Assemblies Exit Ascess	Frame Exterior Interior Exterior Interior	0 Yes Fire Area #1 5b Rating 0 0 0 0 0 titions.	Fire Area #2 5b Rating 0 0 0 0 0 0 0 Incidental Rooms Table 508.2.5 Boiler Room	Fire Area #3 0 Rating 0 0 0 0 0 Hours	1, 2, 3

See Code Plan for locations of rated partitions.

INTERIOR FINISHES

Allowable Finishes Table 803.9	Fire Area #1	Fire Area #2	Fire Area #3
Exits and Exit Passageways	В	В	В
Exit Access Corridors	С	С	С
Other Areas	С	С	С

OCCUPANT LOAD

Refer to Code Floor Plan for occupancy load per room. Classification		1004.1.1 Building A	Building B	Building C	Total	
0.000000	Educational		Dullallig 71	Building B	Building 0	635
	Classrooms	20sf/person gross	70	550		000
	Library (Reading)		10	550		
	Library (Stacks)	•	5			
	Assembly	15sf/person net		765		765
	Business					28
	Kitchen	200sf/ person gross		6		
	Offices	100sf/person gross	18	4		
		TOTAL	103	1325		1428

Refer to Code Plan for Egress, Exit Access, Maximum Travel, Maximum Common Path and Maximum Dead End Corridor.

MEANS OF EGRESS

		Required		Provided/Worst Case
Number of Exits	Under 49 occ.	1	1006.2.1	1
	Over 49 under 500	2	1006.2.1	2
	Over 500 under 100	3	1006.2.1.1	3
Common Path of Tr	ravel	75	Table 1006.2.1	46
Exit Access Travel I	Distance	250	Table 1017.2	141
Dead End Corridor		50	1020.4(2)	16

PLUMBING REQUIREMENTS

	Classification	Required Water Closets	2902.1 Lavatories	Showers	Drinking Fountains	Service Sink
Primary Use	E	13	13	-	7	1
Accessory Use	Α				2	1
	Men	4	2	-		
	Women	6	2	-		
	В	2	1	-	1	1
		Provided				

Primary Use Accessory Use	

	Water Closets	Lavatories	Showers
	10	5	1
Men	4	2	-
Women	4	3	-
	4	4	-
	COMPLIANT	NON-COMPLIANT	COMPLIANT

(if shared)

NON-COMPLIANT	COMPLIANT

Drinking Fountains Service Sink

Uses are not subject to simultaneous occpancy so therefore fixtures can be shared between uses. This does require that toilet facilities in other parts of the building from the gymnasium be open when the gym is in use.

ENERGY CODE

Using Prescriptive Method for compliance

Е

		Required	Provided
Roof	(Attic and Other)	R-38	UNK
Walls	(Wood Framed)	R-20	COMPLIANT
Bewlow Grade		R-7.5ci	COMPLIANT
Heated Slabs		R-15 for 24"	N/A
Doors		U-0.70	UNK
Windows		U-0.35	UNK

Emerson Elementary School Existing Building Needs

 Area
 1st Floor
 2nd Floor
 Total

 29,532
 32,846

 Perimeter
 280
 1,415
 1,695

						Cost /	Priority	
Cat	ltem	Existing Descriptions	Corrective Measure	High	1	Medium	Low	Future
	Minimum Size Lot Water and Septic	26 acres with long-term lease. On-site water and sewer. New well. Septic system probably 20 +/- years old.	The septic system at some point will need to be replaced or at least serviced.					\$ 50,000
Site	3 Bus/Car Separation 4 Parking		replaced of at least serviced.					
℧	5 Playground/Playfields	Adequate parking.						
	6 Site Features 7 Grading/Drainage	Drainage recently improved.						
	8 Oil, Propane Tank Age/Condition 9 Roof Condition	New on-site underground propane Original school has a newer roof. The additions are			Ş	100,000		
		in poor condition. The 1950 and 1999 wings need a new roof.	completed in the last year.	.				
e d	10 Wall Condition (insulation and moisture protection)	Some mildew, crackes or missing pieces of vinyl. Exposed wood needs paint touch-up. Some ice-	Investigate the source of the mold, repair and clean.	\$ 10	0,000			
Envelope	11 Door Condition (energy efficiency and operation)	damming occuring. Split-Faced Block shows mold. Most doors in resonably good condition. The						
ш		weather seals need replacing. The pump room doors need paint.						
	12 Window Condition (energy efficiency and 13 Foundation Condition (insulation and moisture	All windows in are old or in poor condition.	Replace all windows.	\$ 125	,000			
	protection) 14 K-2 location based on LED							
	15 Panic devices 16 Stair Details (Rise/Run, Railings)	Stair guardrails and handrails do not meet current	Upgrade guardrails and handrails. Reconfigure	\$ 8	,000		\$ 120,000	
	17 Areas of Refuge	code. Original front steps are too steep.	original front steps.					
	18 Capacity of Means of Egress 19 Corridor Width	The lower level corridor is too narrow being less	Reconfigure lower level to meet code for corridor	\$ 20	0,000			
	20 Number of Exits	than 6'-0" wide.	width and other issues.					
Life Safety	21 Dead-end Corridors22 Exits through Intervening Rooms							
Life	23 Door Arrangement 24 Travel Distance							
	25 Means of Escape 26 Protection of Vertical Openings	The stairs and lift to lower level not rated.	Reconfigure and fire rate stairs and lift openings.	\$ 20	,000			
	27 Protection of Hazards 28 Protection of Corridors		J. 11. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	,	,			
	29 Smoke Compartments 30 Fire Alarm, Emergency lights and Exit lighting	New system installed recently.						
	31 Furnishings, Decorations and Personal Effects in the Corridor	nen system instance recently.						
Code	32 Height and Area Limitations 33 Construction Classification							
Building C	34 Fire Rated Construction 35 Sprinklers	The building has an automatic sprinkler system.						
Bui	36 Fire Protection 37 Snow Load Capacity	The butuing has an automatic sprinker system.						
ctural	38 Wall Condition (seismic capacity, cracks or deflection)							
Structui	39 Floor Load Capacity 40 Foundation Condition (cracks or rot)							
	41 Parking 42 Building Access	Complies Complies						
.₹	43 Accessible Route 44 Clearances	Some corridor doors do not have proper clearances.	Reconfigure doorways for clearance.	\$ 10	,000			
Accessibility	45 Door Hardware 46 Stair Details							
Acc	47 Toilet Facilities	Not all comply.	Upgrade toilet rooms that are not fully handicap accessible.		Ş	75,000		
	48 Signage 49 Elevator	There is a lift only to the lower level.						
ental	50 Ventilation	Existing system is older unit ventilators with some areas of ducted fan-coils.	Provide VRF heat pumps.		Ş	825,000		
Environmental Quality	51 Thermal Control	Some rooms overheating.	Recommission system and provide a digital control system.		Ş	215,000		
	52 Moisture / Mold 53 Lighting Quality	High humidity experienced in the lower level. Old energy inefficient flourescent lights.	Povide commercial dehumidification. Upgrade to new LED lights.		3	-,		
Indoor	54 Acoustics 55 Sanitation							
	56 Boiler Condition and Distribution57 Water Supply	Boilers replaced recently.						
	58 Plumbing / Fixture Count 59 Kitchen Equipment			\$ 125	,000			
ices	60 Main Electrical Service 61 Generator	Aging but in reasonably good condition. No generator.	Consider replacing at some point.					\$ 50,000
Build. Services	62 Power Distribution	Aging and should be upgraded. Outlets should be replaced, wiring checked and additional power for					\$ 65,000	
Buile	63 Lighting Efficiency	technology provided.						
	64 Site lighting	Site lighting is minimal.	Add LED sharp-cut-off site lights for security and safety.		Ş	20,000		
	65 Roof Drains 66 Phone, Intercom, Security	System is aging and should be upgraded.	Install new integrated phone-intercom with VOIP.				\$ 30,000	
	67 Ceilings 68 Walls	Most ceilings are drywall. Some have fiberglass Some walls show significant wear.	Install new suspended ceilings. Repair as needed	\$ 25	0,000 5,000			
Interior	69 Floors 70 Doors	Some floor tiles need to be replaced.		\$ 100	,000			
Inte	71 Cabinetry 72 Fixed Equipment	Classrooms lack cabinetry.	Add cabinets to meet district standard.		Ş			
	73 Visual Display Boards	The white boards and tack boards are adequate but do not up to date with current display technology.	standard.		Ş	21,000		
₹	74 Lock-down of public areas	The gymnasium can only be locked down from the public through the use of gates. This is not Life	Install security doors and upgrade toilet facilities.	\$ 20	0,000			
nd Safety	75 Secure Visitor Check-in	Safety Code compliant. The current vestibule is remote from the secretaries		\$ 100	,000			
ırity and	76 Technology	office. School has cameras.	main office with a secure window between.					
Security	77 Physical Hazards78 Hazardous Materials							
	79 Visibility 80 Miscelaneous upgrades including access to exterior				Ç	6,000		
reous	mechanical door. 81							
Miscelaneous	82 83							
Σ	84 85							
						5 1,488,000		

TTG Study Recommendations Changes to TTG Study Barker Recommendations \$ 603,000 \$ 1,488,000 \$ 215,000 \$ 100,000

Total Renovations \$ 2,406,000

Value of Renovation Renovation

Cost Existing Minimum Maximum

State Funding Thresholds \$ 178 \$ 5,846,588 \$ 1,461,647 \$ 3,507,953 Per/S.F.

Emerson Elementary School

Curriculum Worksheet

Design Capacity	200
Core Capacity (Theoretical Max.)	250
Periods Per Day	6
Number of grades (include K)	7

		Number of	grades (in	ades (include K)		7	7	
<u>Subject</u>	Avg. Students/ grade	Avg. Size		Max. Students/ grade	Max Size		Teaching Stations	
Pre-Kindergarten	9	16		18	18		1.0	
Kindergarten (1) General Classrooms	27	16		36	18		2.0	
1 Grade Classrooms	27	18		40	20	2.0		
2 Grade Classrooms	27	18		40	20	2.0		
3/4 Grade Classrooms (4)	55	20		66	22	3.0		
5/6 Grade Classrooms (4)	55	20		66	22	3.0		
				Genera	l Classroom	Total	10.0	
	% enrolled	Total	Max Size	М	eetings / Wee	k	Required Stations	
Special Ed. /Specialists (2) ACES Title I OT / PT Speech Reading	20%	50	6		10		3.0	
Regular Ed Special Rooms Science								
Art	100%	250	25		1		1.0	
Music	100%	250	25		1		0.0	
Phys. Ed.	100%	250	25		2		1.0	(3)

¹ Kindergarten is full day.

- Actual Special Ed and Specialists required spaces varies considerably from school to school.
- 2 Secialists include regular ed small group instruction. Above calculation is solely for computing purposes. Required spaces should be base on actual programs.
- 3 Gymnasium to be designed for 2 teachings stations simultaneously.
- 4 Multi-Age classrooms employed to create more efficient class sizes.

Table E

Barker Architects, PLLC 11/17/2019

Emerson Elementary School

Space Needs Worksheet

Design Capacity 200 Core Capacity 250

	ELEMENT		DESIG	١	EXISTING			COMMENT	
		#	SIZE	TOTAL	#	SIZE	TOTAL		
ES	Pre-Kindergarten	1	1000	1000				0%	
AC	Kindergarten	2	1000	2000	2	1007	2014	101%	
EDUCATIONAL SPACES	Classrooms	10	900	9000	8	881	7049		Some Classrooms slightly below DOE recommendations
CATIO	Art	1	1000	1000	1	1020	1020	102%	
ă	Music								
Ш	Special Ed. /Specialists	3	360	1080	9	360	3240	300%	
	Phys Ed			5600			5583	100%	
	Food Service								
	Caf. / Multi-Purpose Rm						0	#DIV/0!	
	Kitchen			583			697	119%	
ES	Assembly			1000			605	61%	
SPACES	Library			1800			1228	68%	
В	Stacks	1	1400						
CORE	Computer	1	400						
Ū	Offices			1200			2047	171%	
	Admin./Guid.		900			1675			
	Faculty / Work		0			258			
	Nurse		300			114			
	Subtotal			24263			23483		
	MiscCirc, Mech, Toilets, Janitor Storage		40%	9705			9363		

Totals	33969	32846
Sq. Ft. / Student (Design Cap.)	170	164
Sq. Ft. / Student (Core Cap.)	136	131

Table F

Barker Architects, PLLC

11/17/2019

Gilsum Elementary School



View of Community Center entrance



View of school entrance in the courtyard.



View of Gymnasium.



Typical cafetera.



Exterior of kindergarten.

Note the steep grades making a second exit difficult.

Also, note the buried tanks.



View of extensive network of ramps used as an exit discharge.

Note the lack of guardrails from the higher levels.



KEY PLAN

CONSULTANTS



P: (603)731-7796 WWW.BARKERARCHITECTS.COM


MONADNOCK REGIONAL SCHOOL DISTRICT ELEMENTARY SCHOOLS ASSESSMENT STUDY GILSUM STEAM ACADEMY EXISTING SITE PLAN


DATE: OCTOBER 31, 2019 SCALE: AS NOTED

EX1

KEY PLAN

CONSULTANTS





8 KEARSARGE STREET CONCORD, NH 03301 P: (603)731-7796 WWW.BARKERARCHITECTS.COM


MONADNOCK REGIONAL SCHOOL DISTRICT ELEMENTARY SCHOOLS ASSESSMENT STUDY

GILSUM STEAM ACADEMY EXISTING CONDITIONS PLANS




SCALE









ASSEMBLY DIAGONAL DISTANCE ASSEMBLY EXIT REMOTENESS

DATE: OCTOBER 31, 2019 SCALE: AS NOTED

STORAGE 1410 SF 5 OCC. 3

BASEMENT FLOOR PLAN

KEY PLAN

P: (603)731-7796 WWW.BARKERARCHITECTS.COM

CUTLER ELEMENTARY SCHOOL EXISTING CONDITIONS PLANS

DATE: OCTOBER 31, 2019 SCALE: AS NOTED



OBASEMENT FLOOR PLAN

BASIC INFORMATION							
Location:	AREA	В	uilding A	Building B	Building C	Total	
640 Rte 10	1st Floor		10178	7890			18068
Gilsum, NH 03448	2nd Floor						0
	3rd Floor						0
	Total		10178	7890			18068
	04:		4	4			
	Stories		1	1			
	Height		24	24			
	Footprint		10178	7890			
	Perimeter		456	562.5			912
	Const. Class	5b	5b				5b
	Building Type	S1	S1				
	Frontage min. 20'		263.5	276.5			
	Frontage min. 30'		62.5	276.5			
	Weighted Width		22.4	30	#DIV/0!		
	-						

APPLICABLE CODES

NEW HAMPSHIRE STATE BUILDING CODE

2015 EDITION INTERNATIONAL BUILDING CODE (IBC)

2015 EDITION INTERNATIONAL ENERGY CONSERVATION CODE (IECC)

2015 EDITION INTERNATIONAL EXISTING BUILDING CODE (IEBC)

2015 EDITION INTERNATIONAL MECHANICAL CODE (IMC)
2015 EDITION INTERNATIONAL PLUMBING CODE (IPC)
2017 EDITION NATIONAL ELECTRICAL CODE (NEC)

NEW HAMPSHIRE SAF-C 6000 BUILDING SAFETY CODE

2015 EDITION NFPA 1 UNIFORM FIRE CODE 2015 EDITION NFPA 101 LIFE SAFETY CODE

NEW HAMPSHIRE BARRIER FREE DESIGN CODE

2010 EDITION ADA STANDARDS FOR ACCESSIBLE DESIGN

NH DEPT OF EDUCATION STANDARDS

Approval of plan set by the State Fire Marshal required. Designs to meet the following codes:

State of NH Fire Code

2015 NFPA 101 - Life Safety Code

NH Code for Barrier Free Design and 2010 ADAAG when applicable

ANSI S12.60 Acoustical Performance Criteria, Design Requirements and Guidelines for Schools

Grade Level Elementary (Elementary, Middle, High)

Design Capacity: 125 sudents Core Capacity: 160 sudents

Max. Building Size: Max. Construction:

Minimum Size Standards

	Minimum Value	Preferred Total
Classrooms	36 s.f. per student	900 s.f.
Kindergartens	50 s.f. per student	1000 s.f.
Library	40 s.f. per student	1800 s.f.
Phys. Ed.	110 s.f. per student	700 s.f.
Office	60 s.f. per person	1200 s.f.
Nurse	1 cot per 200 stud.	300 s.f.

Total

2101

34653

BUILDING DATA Use and Occupancy Classification Building A Building B Building C Total 25904 Primary Use Educational 11167 12636 2101 Area by Use Accessory Use Assembly 1115 5157 6272 Business 180 1757 1937 Storage 540 540 Misc.

12462

20090

Mixed Use No Construction Type NFPA 13 30.3.5.2 Sprinklers Yes Fire Alarm System Yes 30.3.4.1.1

Refer to Code Plan for Use Area Locations.

OCCUPANT LOAD)				
Classification	7.3.1.2				
		Building A	Building B	Building C	Total
Educational					276
Classrooms	20sf/person	265			
Library (Readin	ng) 50sf/person net	7			
Library (Stacks	100sf/person	4			
Assembly					735
Non-Concentra	te 15sf/person net		69		
Concentrated	7sf/person net		640		
Stage	15sf/person net		26		
Locker room	50sf/person				
Business	,				12
Offices	100sf/person	10			
Kitchen	200sf/ person		2		
	h. 300sf/ person		_		
e.e. ago a mooi	5555., p316611				
	Total	286	737	0	1023
	Total	200	7.07	3	1020

Refer to Code Plan for occupancy load per room.

MEANS OF EGRESS						
		New Educational	Exist Educational	Provided		
Location of PK, K and 1st Grade	LED	14.2.1.2	15.2.1.2	COMPLIANT		
Corridor Width	6'-0"	14.2.3.2	15.2.3.2	COMPLIANT		
Number of Exits	2	14.2.4	15.2.4	NON-COMPIANT	Building A	
Rooms Over 1000 sf	2	14.2.5.4	15.2.5.4	NON-COMPIANT	Kindergarten	
Assembly over 500	3	7.4.1.2	7.4.1.2	COMPLIANT	-	
Dead End Corridor	50'	14.2.5.2	15.2.5.2	COMPLIANT		
Common Path of Travel	100'	14.2.5.3.2	15.2.5.3.2	COMPLIANT		
Travel Distance to Exit	200'	14.2.6.2	15.2.6.2	COMPLIANT		
Windows for Rescue	No	14.2.11.1.2(2)	15.2.11.1.2(2)	SPRINK. EXCEPT.		

Refer to Code Plan for Egress, Exit Access, Maximum Travel, Maximum Common Path and Maximum Dead End Corridor.

	Hours			Hours	
Exit Stairs	1		Hazardous Rooms		
Shafts	1		Boiler Room	SPRINKLER	15.3.2.1
Horizontal Assemblies	1		Storage Room	SPRINKLER	15.3.2.1
Exit Access Corridors	S	14.3.6(2)	Janitor Closet	SPRINKLER	15.3.2.1
Smoke Compatments	N/A	14.3.7.2(2)			

See Code Plan for locations of rated partitions.

INTERIOR FINISHES	
Allowable Finishes	Class
Exits and Exit Passageways	A
Exit Access Corridors	В
Other Areas	С

BUILDING DATA					
Use and Occupanc	y Classification				
Building A	Primary Use	E		Number of Stories	1
Fire Area #1	Accessory Use	Α		Height	24 LF
	Accessory Use	В	m	1st Floor	10178 SF
			Area	2nd Floor	0 SF
	Mixed Use	No	*	3rd Floor	0
	Construction Type	5b		Footprint	10178 LF
	Sprinklers	Yes		Perimeter	456 LF
	Building Type	S1		Frontage	263.5 LF
				Weighted Width	22.4 LF
This Fire Area	does	Meet Code for Heigh	This Fire Area	is	Within Allowable Area
Building B	Primary Use	A-3		Number of Stories	1
Fire Area #2	Accessory Use	E		Height	24.00 LF
	,		_	1st Floor	7890 SF
			Area	2nd Floor	0
	Mixed Use	No	<	3rd Floor	0
	Construction Type	5b		Footprint	7890 LF
	Sprinklers	Yes		Perimeter	562.5 LF
	Building Type	S1		Frontage	276.5 LF
				Weighted Width	30 LF
This Fire Area	does	Meet Code for Heigh	This Fire Area	is	Within Allowable Area
Building C	Primary Use	Е		Number of Stories	0
Fire Area #3	Accessory Use	_	Area	Height	0 LF
	,			1st Floor	0 SF
				2nd Floor	0
	Mixed Use	No		3rd Floor	0
	Construction Type	5b		Footprint	0 LF
	Sprinklers	Yes		Perimeter	0 LF
	Building Type	S1		Frontage	0 LF
				Weighted Width	#DIV/0! LF
This Fire Area	does	Meet Code for Heigh	This Fire Area	#DIV/0!	Within Allowable Area
		Fire Area #1	Fire Area #2	Fire Area #3	
Separated Uses		0	0	0	
Fire Alarm System		Yes	Yes	Yes	
Existing Building Al	teration Level				1, 2, 3
CONSTRUCTION C	LASSIFICATION				
Table 601		Fire Area #1	Fire Area #2	Fire Area #3	
		5b	5b	5b	
Element		Rating	Rating	Rating	
Primary Structural I	- rame	0	0	0	
Bearing Walls	Exterior	0	0	0	
	Interior	0	0	0	
Non Bearing	Exterior	0	0	0	
	Interior	0	0	0	
Floors		0	0	0	
Roofs		0	0	0	
See Code Plan for I	ocations of rated par	titions.			
PROTECTION					
	Hours		Incidental Rooms	Hours	
	i ioui a		moldomai Nooms	i ioui a	

See Code Plan for locations of rated partitions.

2

Smoke

Table 706.4

708.4

709.1

708

712

1018.1

Table 707.3.9

Table 508.2.5

Boiler Room

Sprinkler Room

Firewalls

Shafts

Fire Barriers

Fire Partitions Exit Stairs

Exit Access

Horiz. Assemblies

		\sim			HES
INI	ıeri	OR	+11	VII.S	HES

Allowable Finishes Table 803.9	Fire Area #1	Fire Area #2	Fire Area #3
Exits and Exit Passageways	В	В	В
Exit Access Corridors	С	С	С
Other Areas	С	С	С

OCCUPANT LOAD

Classification	1004.1.1				
		Building A	Building B	Building C	Total
Educational					276
Classrooms	20sf/person gross	265			
Library (Reading)	50sf/person net	7			
Library (Stacks)	100sf/person gross	4			
Assembly					735
Non-Concentrate	15sf/person net		69		
Concentrated	7sf/person net		640		
Stage	15sf/person net		26		
Locker room	50sf/person				
Business		0			12
Offices	100sf/person gross	10			
Kitchen	200sf/ person gross	0	2		
Storage & Mech.	300sf/ person	0			
	TOTAL	286	737	0	1023

Refer to Code Plan for Egress, Exit Access, Maximum Travel, Maximum Common Path and Maximum Dead End Corridor.

MEANS OF EGRESS

		Required		Provided/Worst Case
Number of Exits	Under 49 occ.	1	1006.2.1	1
	Over 49 under 500	2	1006.2.1	2
	Over 500 under 100	3	1006.2.1.1	3
Common Path of T	ravel ravel	75	Table 1006.2.1	46
Exit Access Trave	Distance	250	Table 1017.2	141
Dead End Corridor		50	1020.4(2)	16

PLUMBING REQUIREMENTS

	Classification	Required Water Closets	2902.1 Lavatories	Showers	Drinking Fountains	Service Sink
Primary Use	E	6	6	-	3	1
Accessory Use	Α				2	1
	Men	3	2	-		
	Women	6	2	-		
	В	1	1	-	1	1

Primary Use E Accessory Use A Men Women

Provided Water Closets	Lavatories	Showers	Drinking Fountains	Service Sink
8	6	1	0	0
			0	
1	1	-		
1	1	-		
1	1	-	0	

NON-COMPLIANT NON-COMPLIANT COMPLIANT

NON-COMPLIANT NON-COMPLIANT

Uses are not subject to simultaneous occpancy so therefore fixtures can be shared between uses. This does require that toilet facilities in other parts of the building from the gymnasium be open when the gym is in use.

ENERGY CODE

Using Prescriptive Method for compliance

В

	·	Required	Provided	
Roof	(Attic and Other)	R-30ci	COMPLIANT	Only in 1996 addition. NON-COMPLIANT elsewhere
Walls	(Wood Framed)	R-11.4ci	COMPLIANT	Only in 1996 addition. NON-COMPLIANT elsewhere
Bewlow Grade		R-7.5ci	COMPLIANT	Only in 1996 addition. NON-COMPLIANT elsewhere
Heated Slabs		R-15 for 24"	N/A	
Doors		U-0.70	NON-COMPLIANT	Unknown
Windows		U-0.35	NON-COMPLIANT	Unknown

Gilsum Elementary School Existing Building Needs

 1st Floor
 Total

 Area
 18,068
 18,068

 Perimeter
 912
 912

				Perimeter	1 912		912
Cat	ltem	Existing Descriptions	Corrective Measure	High	Cost / Medium	Priority Low	Future
	1 Minimum Size Lot 2 Water and Septic	The site is owned by the town. On-site water and sewer and fire cistern dating to the 1980's.	At some point the septic system will need to be replaced. Other systems will required maintenance			\$ 50,000	
	3 Bus/Car Separation	The limited driveway space does not provide adequate car and bus separation, but due to the	as they age.				
Site	4 Parking/Drives 5 Playground/Playfields	small enrollment it is not currently an issue.					
	6 Site Features 7 Grading/Drainage	Handicap Ramp in disrepair. On-site drainage. Courtyard hard to drain and keep	Repair ramp. Rebuild ramp Reconfigure courtyard to drain properly.			\$ 250,000	
	8 Oil, Propane Tank Age/Condition	clear of snow. On-site underground oil tank that is 20+ years old. Its			\$ 40,000		
	9 Roof Condition	location makes it difficult to replace. The asphalt shingles appear to be at the end of their expected life. Ice damming occuring.	Replace roof shingles. Improve roof edge insulation. Reconfigure canopy to shed water more efficiently.	\$ 70,000	\$ 5,000		
be	10 Wall Condition (insulation and moisture protection)	expected life. Ice dailining occurring.	Some work already completed.				
	11 Door Condition (energy efficiency and operation) 12 Window Condition (energy efficiency and operation)	Windows in 1970's wing appear to be nearing the end of their useful life.	Repair or cover gaps at window sills	\$ 30,000			
	13 Foundation Condition (insulation and moisture protection)	end of their diserul life.					
	14 K-2 location based on LED 15 Panic devices						
	16 Stair Details (Rise/Run, Railings) 17 Areas of Refuge	Handrails at exterior stair at music room does not meet code.	Replace with code complaint handrail.		\$ 4,000		
	18 Capacity of Means of Egress 19 Corridor Width						
<u>Ş</u>	20 Number of Exits 21 Dead-end Corridors 22 Exits through Intervening Rooms						
<u>ē</u>	23 Door Arrangement 24 Travel Distance						
	25 Means of Escape 26 Protection of Vertical Openings 27 Protection of Hazards						
	28 Protection of Corridors 29 Smoke Compartments						
	30 Fire Alarm, Emergency lights and Exit lighting 31 Furnishings, Decorations and Personal Effects in the	Current system 20 years old and archaic.	Replace with new addressable system.		\$ 50,000		
ŏ	Corridor 32 Height and Area Limitations 33 Construction Classification						
uilding	34 Fire Rated Construction 35 Sprinklers	The building has an automatic sprinkler system.					
_	36 Fire Protection37 Snow Load Capacity38 Wall Condition (seismic capacity, cracks or deflection)						
Struct	39 Floor Load Capacity						
	40 Foundation Condition (cracks or rot) 41 Parking 42 Building Access	Not well defined.					
	43 Accessible Route 44 Clearances	Some interior ramps are too steep.	Rebuild ramps to meet ADAAG.			\$ 25,000	
Acce	45 Door Hardware 46 Stair Details 47 Toilet Facilities	The			\$ 135,000		
	48 Signage 49 Elevator	The current gang toilets are not handicap accessible. N/A			3 153,000		
Environmental Quality	50 Ventilation	Lack of proper ventilation through majority of building. Gymnasium appears adequate. 1970's wing has unit ventilators that are blocked and archaic.	Install new ventilation system throughout with the exception of the 1990's wing.	\$ 325,000			
ronmen	51 Thermal Control	There currently is no air conditioning. Control system is archaic.	Add air conditioning in future improvements. Add a DDC system.		\$ 120,000	\$ 125,000	
	52 Moisture / Mold 53 Lighting Quality	High humidity experienced in the lower level.	Povide commercial dehumidification.		\$ 20,000		
Ĕ	54 Acoustics 55 Sanitation 56 Boiler Condition and Distribution	Hydronic system with a variety of delivery methods.	Upgrade heating system.			\$ 160,000	
	57 Water Supply58 Plumbing / Fixture Count	Fixtures are againg.	Upgrade as part of ADA upgrades			\$ 15,000	
ses	59 Kitchen Equipment 60 Main Electrical Service 61 Generator	Updated in the 1990's None					
	62 Power Distribution 63 Lighting Efficiency	Most wiring is Romex and not code compliant. Light fixtures are currently flourescents and not as	Upgrade wiring to metal clad. Replace lighting with LED fixtures.		\$ 90,000	\$ 125,000	
	64 Site lighting 65 Roof Drains	efficient as newer technology. No site lighting beyond buidling lights.	Add fixtures in parking lot.			\$ 10,000	
	66 Phone, Intercom, Security	The phone and intercom are aging.	Replace phone and intercom with an integrated VOIP system.			\$ 25,000	
	67 Ceilings	Most of the ceiling tile throughout the building, with the exception of the 1990's wing should be replaced.	Replace ceiling tiles throughout with the exception of the 1990's wing. $ \\$	\$ 36,000			
	68 Walls 69 Floors	Some floor tiles in poor condition. There may be	Abate and replace aging floor tile.		\$ 20,000		
Interior	70 Doors	hazardous material present. The doors in the most parts of the building with the	Replace doors that are damaged.			\$ 12,000	
	71 Cabinetry 72 Fixed Equipment	exception of the 1990's wing show significant wear. Classrooms lack cabinetry. Basketball backstop not functioning properly.	Add cabinets to meet district standard. Investigate and fix backstop.	\$ 1,500		\$ 38,000	
	73 Visual Display Boards	The white boards and tack boards are adequate but do not up to date with current display technology.	Install new smart TV monitors to match district standard.		\$ 7,500		
	74 Lock-down of public areas 75 Secure Visitor Check-in	Gymnasium can be locked down. No secure check-in. Main office remote from entrance.	Reconfigure main office to be connected to a front entrance.	\$ 100,000			
urity	76 Technology 77 Physical Hazards	School has cameras.			•		
	78 Hazardous Materials 79 Visibility 80 Miscelaneous upgrades including access to exterior	Some asbestos exists in the building. Main office is remote from parking and playfields.	Abate and replace with new material.		\$ 10,000		
	mechanical door. 81 Nurse Station	The nurse' station is in what was previously a kitchen	Renovate nurse' area.			\$ 80,000	
Š	82 83	and is not adequately laid out.					
	83 84 85						
				\$ 562,500	\$ 501,500	\$ 915,000	\$ -
					_		

TTG Study Recommendations Changes to TTG Study Barker Architects Recommendations Total Renovations \$ 1,979,000

 Value of Cost Per S.F.
 Value of Existing
 Renovation Minimum
 Maximum

 State Funding Thresholds
 178
 \$ 3,216,104
 \$ 804,026
 \$ 1,929,662

Gilsum Elementary School

Curriculum Worksheet

Design Capacity	100
Core Capacity (Theoretical Max.)	160
Periods Per Day	6
Number of grades (include K)	7

	Avg.		Max.			
	Students/		Students/			Teaching
<u>Subject</u>	grade	Avg. Size	grade	Max Size		Stations
Pre-Kindergarten						
Kindergarten / Pre-K (1)(4)	14	18	20	20		1.0
General Classrooms (4)						
1/2 Grade Classrooms	29	18	48	24	2.0	
3/4 Grade Classrooms	29	20	48	24	2.0	
5/6 Grade Classrooms	29	22	48	24	2.0	

				General Classroom	Total	6.0	
	% enrolled	Total	Max Size	Meetings / Week		Required Stations	
Special Ed. /Specialists (2) Resource OT / PT Speech Reading	20%	32	6	10		2.0	
Regular Ed Special Rooms							
Science Art	100%	160	25	1		1.0	
Music	100%	160	25 25	1		0.0	
Phys. Ed.	100%	160	25	2		1.0	(3)

- 1 Kindergarten is full day.
- Actual Special Ed and Specialists required spaces varies considerably from school to school.

 Secialists include regular ed small group instruction. Above calculation is solely for computing purposes. Required spaces should be base on actual programs.
- 3 Gymnasium to be designed for 2 teachings stations simultaneously.
- 4 Multi-Age classrooms employed to create more efficient class sizes.

Table E

Barker Architects, PLLC 11/17/2019

Gilsum Elementary School

Space Needs Worksheet

Design Capacity 100 Core Capacity 160

	ELEMENT	[DESIG	V	EXISTING				COMMENT
		#	SIZE	TOTAL	#	SIZE	TOTAL		
S	Pre-Kindergarten								With current low
ACE	Kindergarten / Pre-K	1	1000	1000	1	1337	1337	134%	enrollments, multi-age classrooms work. With any
EDUCATIONAL SPACES	Classrooms	6	900	5400	3	1007	3021	56%	increase, additional classrooms would be needed.
ATIC	Art	1	1000	1000	1	931	931	93%	
) CC	Music								
	Special Ed. /Specialists	2	360	720	0	0	0	0%	
	Phys Ed			5600			4605	82%	
	Food Service								
	Caf. / Multi-Purpose Rm			800			1033	129%	
	Kitchen			373			1362	365%	
SES	Assembly			1000			388	39%	
SPACES	Library			1800			650	36%	
ZE S	Stacks	1	1400						
CORE	Computer	1	400						
	Offices			1200			465	39%	
	Admin./Guid.		900			304			
	Faculty / Work		0			0			
	Nurse		300			161			
	Subtotal			18893			13792		
	MiscCirc, Mech, Toilets, Janitor Storage		40%	7557			4276		

Totals	26451	18068
Sq. Ft. / Student (Design Cap.)	265	181
Sq. Ft. / Student (Core Cap.)	165	113

Table F

Barker Architects, PLLC

11/17/2019

Mt Caesar Elementary School



View of front entrance.



View of side of building.




View of cafeteria.

Note that this is also used for physical education.



Mechanical system in the cafeteria.




Typical corridor.

Note ramp in corridor.




Special Education Space.



This school is mostly upgraded but some areas still show signs of wear such as this door that has been damaged by a door chock.



Typical classroom.



KEY PLAN




KEARSARGE STREET CONCORD, NH 03301

MONADNOCK REGIONAL SCHOOL DISTRICT ELEMENTARY SCHOOLS ASSESSMENT STUDY

MT CEASAR SCHOOL EXISTING SITE PLAN

DATE: OCTOBER 31, 2019 SCALE: AS NOTED

EX1



MAIN FLOOR PLAN

COMMON PATH OF TRAVEL TO 2 MEANS OF EGRESS

ASSEMBLY DIAGONAL DISTANCE ASSEMBLY EXIT REMOTENESS

DATE: OCTOBER 31, 2019 SCALE: AS NOTED



EX3

BASIC INFORMATION					
Location:	AREA	Building A	Building B	Building C	Total
585 Old Homestead Hwy Swanzey, NH 03446	1st Floor 2nd Floor 3rd Floor	25516	4733	8240	38489 0 0
	Total	25516	4733		38489
	Stories	1	1	1	
	Height	18	12	18	
	Footprint	25516	4733	8240	
	Const. Class	5b	3b	2b	
	Building Type	S1	S1	S1	
	Perimeter	684	275.5	392	
	Frontage min. 20'	909	215	293.5	
	Frontage min. 30'	909	215	293.5	
	Weighted Width	30.0	30	30.0	

APPLICABLE CODES

NEW HAMPSHIRE STATE BUILDING CODE

2015 EDITION INTERNATIONAL BUILDING CODE (IBC)

2015 EDITION INTERNATIONAL ENERGY CONSERVATION CODE (IECC)

2015 EDITION INTERNATIONAL EXISTING BUILDING CODE (IEBC)

2015 EDITION INTERNATIONAL MECHANICAL CODE (IMC)
2015 EDITION INTERNATIONAL PLUMBING CODE (IPC)
2017 EDITION NATIONAL ELECTRICAL CODE (NEC)

NEW HAMPSHIRE SAF-C 6000 BUILDING SAFETY CODE

2015 EDITION NFPA 1 UNIFORM FIRE CODE 2015 EDITION NFPA 101 LIFE SAFETY CODE

NEW HAMPSHIRE BARRIER FREE DESIGN CODE

2010 EDITION ADA STANDARDS FOR ACCESSIBLE DESIGN

NH DEPT OF EDUCATION STANDARDS

Approval of plan set by the State Fire Marshal required. Designs to meet the following codes:

State of NH Fire Code

2015 NFPA 101 - Life Safety Code

NH Code for Barrier Free Design and 2010 ADAAG when applicable

ANSI S12.60 Acoustical Performance Criteria, Design Requirements and Guidelines for Schools

Grade Level Elementary (Elementary, Middle, High)

Design Capacity: 275 sudents Core Capacity: 370 sudents

Max. Building Size: Max. Construction:

Minimum Size Standards

	Minimum Value	Preferred Total
Classrooms	36 s.f. per student	900 s.f.
Kindergartens	50 s.f. per student	1000 s.f.
Library	40 s.f. per student	1800 s.f.
Phys. Ed.	110 s.f. per student	700 s.f.
Office	60 s.f. per person	1200 s.f.
Nurse	1 cot per 200 stud.	300 s.f.

Mt Caesar Elementary School

NFPA 101 - Life Safety Code Review

BUILDING DATA							
Use and Occupan	cy Classification						
				Building A	Building B	Building C	Total
Primary Use	Educational	Use		6293	3411	5660	15364
		\supset					
Accessory Use	Assembly	ģ		1489			1489
	Business	Area		2017		590	2607
	Storage	₹		240			240
	Misc.			1313	1322	1990	
			Total	11352	4733	8240	24325
Mixed Use	No						

Mixed Use No

Construction Type V
Sprinklers Ves

Sprinklers Yes NFPA 13 30.3.5.2
Fire Alarm System Yes 30.3.4.1.1

Refer to Code Plan for Use Area Locations.

OCCUPANT LOAD				
Classification	7.3.1.2		 	

1.0.1.2				
	Building A	Building B	Building C	Total
				1073
20sf/person	601	173	285	
) 50sf/person net	9			
100sf/person	5			
				212
e 15sf/person net				
7sf/person net	212			
15sf/person net				
50sf/person				
				43
100sf/person	35		6	
200sf/person	2		•	
300sf/person				
Total	864	173	291	1328
) 50st/person net 100sf/person net 15st/person net 7st/person net 15st/person net 50st/person 100sf/person 200sf/ person 300sf/ person	20sf/person 601) 50sf/person net 9 100sf/person 5 2 15sf/person net 7sf/person net 50sf/person 100sf/person 35 200sf/person 2	20sf/person 601 173) 50sf/person net 9 100sf/person 5 215sf/person net 212 15sf/person net 50sf/person 100sf/person 35 200sf/ person 2 300sf/ person 2	20sf/person 601 173 285) 50sf/person net 9 100sf/person 5 215sf/person net 7sf/person net 50sf/person 100sf/person 35 6 200sf/ person 2 300sf/ person

Refer to Code Plan for occupancy load per room.

MEANS OF EGRESS				
		New Educational	Exist Educational	Provided
Location of PK, K and 1st Grade	LED	14.2.1.2	15.2.1.2	COMPLIANT
Corridor Width	6'-0"	14.2.3.2	15.2.3.2	COMPLIANT
Number of Exits	2	14.2.4	15.2.4	COMPLIANT
Rooms Over 1000 sf	2	14.2.5.4	15.2.5.4	NON-COMPIANT
Assembly over 500	3	7.4.1.2	7.4.1.2	N/A
Dead End Corridor	50'	14.2.5.2	15.2.5.2	COMPLIANT
Common Path of Travel	100'	14.2.5.3.2	15.2.5.3.2	COMPLIANT
Travel Distance to Exit	200'	14 2 6 2	15 2 6 2	COMPLIANT

14.2.11.1.2(2)

15.2.11.1.2(2)

Refer to Code Plan for Egress, Exit Access, Maximum Travel, Maximum Common Path and Maximum Dead End Corridor.

	Hours			Hours	
Exit Stairs	1		Hazardous Rooms		
Shafts	1		Boiler Room	SPRINKLER	15.3.2.1
Horizontal Assemblies	1		Storage Room	SPRINKLER	15.3.2.1
Exit Access Corridors	S	14.3.6(2)	Janitor Closet	SPRINKLER	15.3.2.1
Smoke Compatments	N/A	14.3.7.2(2)			

See Code Plan for locations of rated partitions.

Windows for Rescue

INTERIOR FINISHES		

Allowable Finishes Class
Exits and Exit Passageways A
Exit Access Corridors B
Other Areas C

SPRINK. EXCEPT.

BUILDING DATA					
Use and Occupancy	y Classification				
Building A	Primary Use	A-3		Number of Stories	1
Fire Area #1	Accessory Use	E		Height	18 LF
	Accessory Use	В	m.	1st Floor	25516 SF
			Area	2nd Floor	0 SF
	Mixed Use	No	4	3rd Floor	0
	Construction Type	5b		Footprint	25516 LF
	Sprinklers	Yes		Perimeter	684 LF
	Building Type	S1		Frontage	909 LF
				Weighted Width	30.0 LF
This Fire Area	does	Meet Code for Heigh	This Fire Area	is	Within Allowable Area
Building B	Primary Use	E		Number of Stories	1
Fire Area #2	Accessory Use	В		Height	12 LF
1 110 7 11 00 11 2	Accessory coo	J		1st Floor	4733 SF
			Area	2nd Floor	33 31
	Mixed Use	No	₹	3rd Floor	
	Construction Type	3b		Footprint	4733 LF
	Sprinklers	Yes		Perimeter	275.5 LF
	Building Type	S1		Frontage	215 LF
	3 71			Weighted Width	30 LF
This Fire Area	does	Meet Code for Heigh	This Fire Area	is	Within Allowable Area
Building C	Primary Use	E		Number of Stories	1
Fire Area #3	Accessory Use	В	Area	Height	18 LF
1 110 7 11 00 110	rioddddi'y ddd		711001	1st Floor	8240 SF
				2nd Floor	02 10 01
	Mixed Use	No		3rd Floor	
	Construction Type	2b		Footprint	8240 LF
	Sprinklers	Yes		Perimeter	392 LF
	Building Type	S1		Frontage	293.5 LF
	Building Type	01		Weighted Width	30 LF
This Fire Area	does	Meet Code for Heigh	This Fire Area	is	Within Allowable Area
		Fire Area #1	Fire Area #2	Fire Area #3	
Separated Uses		1 lie Alea #1	1	1 lie Alea #3	
Fire Alarm System		Yes	Yes	Yes	
Existing Building Alt	eration Level	163	163	163	1, 2, 3
CONSTRUCTION CL					
•	ACON IOATION	F: A ".	F: A "0	E: 1	
Table 601		Fire Area #1	Fire Area #2	Fire Area #3	
		5b	3b	2b	
Element	_	Rating	Rating	Rating	
Primary Structural F		0	0	0	
Bearing Walls	Exterior	0	1	0	
Nam Dane'	Interior	0	0	0	
Non Bearing	Exterior	0	0	0	
Парта	Interior	0	0	0	
Floors Roofs		0	0 0	0	
1/0015		U	U	U	
See Code Plan for lo	ocations of rated par	titions.			
PROTECTION					
			Incidental Dooms		

	Hours		Incidental Rooms	Hours
Firewalls	2	Table 706.4	Table 508.2.5	
Fire Barriers	1	Table 707.3.9	Boiler Room	1
Shafts	1	708.4	Sprinkler Room	1
Fire Partitions	1	709.1		
Exit Stairs	1	708		
Horiz. Assemblies	1	712		
Exit Access	Smoke	1018.1		

See Code Plan for locations of rated partitions.

INTERIOR FINISHES Fire Area #1 Fire Area #2 Fire Area #3 Allowable Finishes Table 803.9 Exits and Exit Passageways В В В Exit Access Corridors С С С Other Areas C. C.

OCCUPANT LOAD					
Classification	1004.1.1				
		Building A	Building B	Building C	Total
Educational			_		1073
Classrooms	20sf/person gross	601	173	285	
Library (Reading)	50sf/person net	9			
Library (Stacks)	100sf/person gross	5			
Assembly					212
Non-Concentrate	15sf/person net				
Concentrated	7sf/person net	212			
Stage	15sf/person net				
Locker room	50sf/person				
Business					37
Offices	100sf/person gross	35			
Kitchen	200sf/ person gross	2			
Storage & Mech.	300sf/ person				
	TOTAL	864	173	285	1322

Refer to Code Plan for Egress, Exit Access, Maximum Travel , Maximum Common Path and Maximum Dead End Corridor.

MEANS OF EGRES	SS				
		Required		Provided/Worst Cas	e
Number of Exits	Under 49 occ.	1	1006.2.1	1	
	Over 49 under 500	2	1006.2.1	1	Several rooms over 1,000 and 50 occ.
	Over 500 under 100	3	1006.2.1.1	N/A	
Common Path of ⁻	Travel	75	Table 1006.2.1	48	
Exit Access Trave	I Distance	250	Table 1017.2	126	
Dead End Corrido	r	50	1020.4(2)	12	

PLUMBING REQU	IREMENTS					
	Classification	Required Water Closets	2902.1 Lavatories	Showers	Drinking Fountains	Service Sink
Primary Use Accessory Use	E A	22	22	-	11 1	1 1
•	Men Women	1 2	1 1	-		
	В	2	1	-	1	1
		Provided Water Closets	Lavatories	Showers	Drinking Fountains	Service Sink
Primary Use Accessory Use	E A	21	19	-	1 0	2
,, ,	Men Women			-		
	В	3	2	-	0	
		NON-COMPLIANT	NON-COMPLIANT	COMPLIANT	NON-COMPLIANT	NON-COMPLIAN

Provided

Uses are not subject to simultaneous occpancy so therefore fixtures can be shared between uses. This does require that toilet facilities in other parts of the building from the gymnasium be open when the gym is in use.

ENERGY CODE

Using Prescriptive Method for compliance Required

NON-COMPLIANT Unknown Roof (Attic and Other) R-30ci Walls (Wood Framed) R-11.4ci NON-COMPLIANT Unknown Bewlow Grade R-7.5ci N/A Heated Slabs R-15 for 24" N/A Doors U-0.70 NON-COMPLIANT Unknown Windows NON-COMPLIANT Unknown U-0.35

Assume that latestest addition meets but older sections do not.

Assume that latestest addition meets but older sections do not.

Mt Ceasar Elementary School Existing Building Needs

 1st Floor
 Total

 Area
 38,488
 38,488

 Perimeter
 1,602

Cat	ltem	Existing Descriptions	Corrective Measure	High	Cost / Priority Medium Low Future
	1 Minimum Size Lot	Existing occurptions	corrective measure	_P ,1	LOW TULLIE
Site	2 Water and Septic	On-site water and septic. 20 +/- years old. Soils are good for septic and system should last. Driveways are being reviewed now. Adequate.			
	6 Site Features 7 Grading/Drainage 8 Oil, Propane Tank Age/Condition 9 Roof Condition	Site well drained. New owned proposne buried tanks. New in 2003.	Good for 15 years.		
dola	 10 Wall Condition (insulation and moisture protection) 11 Door Condition (energy efficiency and operation) 12 Window Condition (energy efficiency and operation) 13 Foundation Condition (insulation and moisture protection) 	Recently upgraded. Good condition.			
	14 K-2 location based on LED 15 Panic devices 16 Stair Details (Rise/Run, Railings) 17 Areas of Refuge 18 Capacity of Means of Egress 19 Corridor Width 20 Number of Exits	Recently replaced. There are several classrooms that are over 1000 sf	Install doors to the exterior	\$ 15,000	
Life Safety	21 Dead-end Corridors 22 Exits through Intervening Rooms 23 Door Arrangement 24 Travel Distance 25 Means of Escape 26 Protection of Vertical Openings 27 Protection of Hazards 28 Protection of Corridors 29 Smoke Compartments 30 Fire Alarm, Emergency lights and Exit lighting	without a second means of egress. Replaced in 2012 wit addressable system.		15,000	
Code	 31 Furnishings, Decorations and Personal Effects in the Corridor 32 Height and Area Limitations 33 Construction Classification 	neplaced in 2022 with duditessable system.			
Building Code	36 Fire Protection	The building has an automatic sprinkler system.			
Structural	 37 Snow Load Capacity 38 Wall Condition (seismic capacity, cracks or deflection) 39 Floor Load Capacity 40 Foundation Condition (cracks or rot) 				
Accessibility	 43 Accessible Route 44 Clearances 45 Door Hardware 46 Stair Details 47 Toilet Facilities 	Complies. Complies. Complies with some exceptions.		\$	25,000
Indoor Environmental Quality	48 Signage 49 Elevator 50 Ventilation 51 Thermal Control 52 Moisture / Mold 53 Lighting Quality 54 Acoustics 55 Sanitation	New system with full A/C New web-based digital controls. All new LED.			
es S	56 Boiler Condition and Distribution 57 Water Supply 58 Plumbing / Fixture Count	New boilers. In good condition. Kindergarten and 1st Grade should have separate toilet rooms. There are no toilets dedicated to assembly.	Add toilet rooms to Kindergarten and 1st Grade.		\$ 50,000
Build. Services	59 Kitchen Equipment 60 Main Electrical Service 61 Generator 62 Power Distribution 63 Lighting Efficiency 64 Site lighting 65 Roof Drains 66 Phone, Intercom, Security	Recently replaced. No generator. Recently replaced. Recently replaced. Being reviewed. Recently replaced.			
Interior	67 Ceilings 68 Walls 69 Floors 70 Doors 71 Cabinetry 72 Visual Disable Boards	Recently replaced. Most have been replaced. All new.	Continue upgrades.	\$	75,000
Security and Safety	73 Visual Display Boards 74 Lock-down of public areas 75 Secure Visitor Check-in 76 Technology 77 Physical Hazards 78 Hazardous Materials 79 Visibility	All new. Every classroom has digital displays. No gymnasium so therefore little to no public use. No secure entrance. Main Office somewhat remote from Lobby.	Create new vestibule that is locked with a direct window to the main office.	\$ 100,000	
scelaneous	80 81 82 83 84 85				
				\$ 115,000 \$	100,000 \$ 50,000 \$

Total Renovations \$ 265,000

TTG Study Recommendations

TTG Study Recommendations

Cost Per S.F.

Existing Minimum Maximum

Barker Architects Recommendations

State Funding Thresholds \$ 178 \$ 6,850,864 \$ 1,712,716 \$ 4,110,518

Mt Ceasar Elementary School

Curriculum Worksheet

Design Capacity	275
Core Capacity (Theoretical Max.)	310
Periods Per Day	6
Number of grades (include K)	3

Sub	<u>ject</u>	Avg. Students/ grade /	Avg. Size		Max. Students/ grade	Max Size	Teaching Stations
	Kindergarten lergarten (1)	28 83	16 16		36 108	18 18	2.0 6.0
1 2	Grade Classrooms Grade Classrooms	83 83	18 18		100 100	20 20	5.0 5.0 10.0
		% enrolled	Total	Max Size	Me	eetings / Week	Required Stations
Spe	cial Ed. /Specialists (2) Resource OT / PT Speech Reading	20%	62	6		10	4.0
Reg	ular Ed Special Rooms Science						
	Art Music Phys. Ed. (3)	100% 100% 100%	310 310 310	25 25 25		1 1 2	1.0 0.0 1.0
	, (-)						

¹ Kindergarten is full day.

Table E

Barker Architects, PLLC

11/17/2019

Actual Special Ed and Specialists required spaces varies considerably from school to school.

Secialists include regular ed small group instruction. Above calculation is solely for computing purposes. Required spaces should be base on actual programs.

³ Gymnasium to be designed for 2 teachings stations simultaneously.

Mt Ceasar Elementary School

Space Needs Worksheet

Design Capacity 275
Core Capacity 310

	ELEMENT		DESIG	٧	I EXISTING			COMMENT	
		#	SIZE	TOTAL	#	SIZE	TOTAL		
ES	Pre-Kindergarten	2	1000	2000	2	1173	2345	117%	
AC	Kindergarten	6	1000	6000	5	853	4266	71%	There is a wide range of
EDUCATIONAL SPACES	Classrooms	10	900	9000	9	908	8169	91%	classroom sizes. Some are well below DOE recommendations.
ATIC	Art	1	1000	1000	1	898	898	90%	
) C	Music	0	1000	0	1	893	893		
	Special Ed. /Specialists	4	360	1440	4	847	3388	235%	
	Phys Ed			5600			0	0%	
	Food Service								
	Caf. / Multi-Purpose Rm			1550			1489	96%	Mt Caesar essentially lacks a gymnasium.
	Kitchen			723			350	48%	
SPACES	Assembly			1000			0	0%	
PAC	Library			1800			871	48%	
S ES	Stacks	1	1400						
CORE	Computer	1	400						
	Offices			1240			3101	250%	
	Admin./Guid.		900						
	Faculty / Work		40						
	Nurse		300						
	Subtotal			31353			23425		
	MiscCirc, Mech, Toilets, Janitor Storage		40%	12541		64%	15063		Due to functional obsolescence there is a high level of non-program space.

Iotals	43895	38488
Sq. Ft. / Student (Design Cap.)	160	140
Sq. Ft. / Student (Core Cap.)	142	124

Table F

Barker Architects, PLLC

11/17/2019

Troy Elementary School




Front Entrance.

Note the fencing on the roof to prevent unauthorized access.



Street-side view of school from driveway.



View from lobby to stairs.

Note that the fire doors open onto the ramp.

Also note the stair lift attached to the railing impeding with the railing use.



Doors at the top of the stair open over the stairs and have been notched to clear the stair lift making them not fire rated.



Typical Classroom in original building.



Typical Classroom in addition.



View of gymnasium



Main toilet facilities.



KEY PLAN

CONSULTANTS



8 KEARSARGE STREET CONCORD, NH 03301 P: (603)731-7796 WWW.BARKERARCHITECTS.COM

MONADNOCK REGIONAL SCHOOL DISTRICT ELEMENTARY SCHOOLS ASSESSMENT STUDY

TROY ELEMENTARY SCHOOL EXISTING SITE PLAN

DATE: OCTOBER 31, 2019 SCALE: AS NOTED

EX1





	CODE NOTES
1	PRESCHOOL THRU 1ST GRADE RESTRICTED TO LED
2	MINIMUM CORRIDOR WIDTH OF 6'-0" REQUIRED
3	TWO SEPARATE EXITS REQUIRED
4	DEAD-END CORRIDOR NOT TO EXCEED 50'-0"
5	COMMON PATH NOT TO EXCEED 100'-0"
6	ROOMS LARGER THAN 1000 SF REQUIRE 2 EXITS
7	DOORS CANNOT INTERFERE WITH CORRIDOR TRAVEL
8	TRAVEL DISTANCE TO EXIT CANNOT EXCEED 200'-0"
9	CORRIDORS ARE REQUIRED TO BE SMOKE RESISTANT
10	EXITS ARE REQUIRED TO BE FIRE RATED
11	ROOMS ARE REQUIRED TO BE FIRE RATED
12	MULTIPLE EXITS ARE REQUIRED TO BE REMOTE
13	OCCUPANT LOAD CANNOT EXCEED EGRESS WIDTH
14	ADA REQUIRES ACCESSIBLE ROUTE
15	ADA REQUIRES ACCESSIBLE FIXTURES

LEGEND

EXIT WITH OCCUPANT LOAD (ABOVE) CAPACITY (BELOW)

REQUIRED FIRE RATED AREA


ASSEMBLY DIAGONAL DISTANCE


ASSEMBLY EXIT REMOTENESS

LONGEST COMMON PATH OF TRAVEL TO 2 MEANS OF EGRESS

LONGEST TRAVEL DISTANCE TO EXIT

OCCUPANT LOAD AND EGRESS DIRECTION





5/6 GRADE CLASSROOM 745 SF 38 OCC

RESOURCE CLASSROOM
745 SF
38 OCC.

4 GRADE CLASSROOF 709 SF 36 OCC.

THIRD FLOOR PLAN



8 KEARSARGE STREET CONCORD, NH 03301 P: (603)731-7796 WWW.BARKERARCHITECTS.COM

> MONADNOCK REGIONAL SCHOOL DISTRICT ELEMENTARY SCHOOLS ASSESSMENT STUDY TROY ELEMENTARY SCHOOL EXISTING CONDITIONS PLANS

DATE: OCTOBER 31, 2019 SCALE: AS NOTED



KEY PLAN

CONSULTANTS



P: (603)731-7796 WWW.BARKERARCHITECTS.COM

MONADNOCK REGIONAL SCHOOL DISTRICT ELEMENTARY SCHOOLS ASSESSMENT STUDY

CUTLER ELEMENTARY SCHOOL EXISTING CONDITIONS PLANS

DATE: OCTOBER 31, 2019 SCALE: AS NOTED

Troy Elementary School

General Conditions

BASIC INFORMATION						
Location:	AREA	Building A	Building B	Building C	Total	
44 School St	1st Floor	5032	12712			17744
Troy, NH 03465	2nd Floor	4966				4966
	3rd Floor	4966				4966
	T	44004	10710			07070
	Total	14964	12712			27676
	Stories	3	1			
	Height	45	24			
	Footprint	5032	12712			
	Perimeter	316	562.5			
	Const. Class	3b	3b			
	Building Type	SM	S1			
	Frontage min. 20'	290	488			
	Frontage min. 30'	290	488			
	Weighted Width	30.0	30.0	#DIV/0!		

APPLICABLE CODES

NEW HAMPSHIRE STATE BUILDING CODE

2015 EDITION INTERNATIONAL BUILDING CODE (IBC)

2015 EDITION INTERNATIONAL ENERGY CONSERVATION CODE (IECC)
2015 EDITION INTERNATIONAL EXISTING BUILDING CODE (IEBC)
2015 EDITION INTERNATIONAL MECHANICAL CODE (IMC)
2015 EDITION INTERNATIONAL PLUMBING CODE (IPC)
2017 EDITION NATIONAL ELECTRICAL CODE (NEC)

NEW HAMPSHIRE SAF-C 6000 BUILDING SAFETY CODE

2015 EDITION NFPA 1 UNIFORM FIRE CODE 2015 EDITION NFPA 101 LIFE SAFETY CODE

NEW HAMPSHIRE BARRIER FREE DESIGN CODE

2010 EDITION ADA STANDARDS FOR ACCESSIBLE DESIGN

NH DEPT OF EDUCATION STANDARDS

Approval of plan set by the State Fire Marshal required. Designs to meet the following codes:

State of NH Fire Code

2015 NFPA 101 - Life Safety Code

NH Code for Barrier Free Design and 2010 ADAAG when applicable

ANSI S12.60 Acoustical Performance Criteria, Design Requirements and Guidelines for Schools

Grade Level Elementary (Elementary, Middle, High)

Design Capacity: 200 sudents Core Capacity: 300 sudents

Max. Building Size: Max. Construction:

Minimum Size Standards

	Minimum Value	Preferred Total
Classrooms	36 s.f. per student	900 s.f.
Kindergartens	50 s.f. per student	1000 s.f.
Library	40 s.f. per student	1800 s.f.
Phys. Ed.	110 s.f. per student	700 s.f.
Office	60 s.f. per person	1200 s.f.
Nurse	1 cot per 200 stud.	300 s.f.

27676

BUILDING DATA						
Use and Occupar	ncy Classification					
			Building A	Building B	Building C	Total
Primary Use	Educational	o o	7581	2508		10089
Accessory Use	Assembly	ž		6696		6696
	Business	À	1165	728		1893
	Storage	e a	314	170		484
	Misc	- - -	5904	540		6444

Total

14964

12712

 Mixed Use
 No

 Construction Type
 V

 Sprinklers
 Yes
 NFPA 13 30.3.5.2

 Fire Alarm System
 Yes
 30.3.4.1.1

Refer to Code Plan for Use Area Locations.

OCCUPANT LOAD					
Classification	7.3.1.2				
Ciassilication	1.3.1.2	Building A	Building B	Building C	Total
Educational		Dulluli ig A	Dulluli ig D	Building C	478
Classrooms	20sf/person	336	127		470
	i) 50sf/person net	10	121		
Library (Stacks)	', '	5			
Assembly	10001/p010011	3			882
,	e 15sf/person net				002
Concentrated	7sf/person net		816		
	15sf/person net				
Stage	•		66		
Locker room	50sf/person				
Business					18
Offices	100sf/person	13	4		
Kitchen	200sf/ person		1		
Storage & Mech.	. 300sf/ person				
	Total	364	1014	0	1378

Refer to Code Plan for occupancy load per room.

MEANS OF EGRESS					
		New Educational	Exist Educational	Provided	
Location of PK, K and 1st Grade	LED	14.2.1.2	15.2.1.2	NON-COMPIANT	1/2 classroom
Corridor Width	6'-0"	14.2.3.2	15.2.3.2	COMPLIANT	
Number of Exits	2	14.2.4	15.2.4	NON-COMPIANT	Building A
Rooms Over 1000 sf	2	14.2.5.4	15.2.5.4	COMPLIANT	-
Assembly over 500	3	7.4.1.2	7.4.1.2	COMPLIANT	
Dead End Corridor	50'	14.2.5.2	15.2.5.2	COMPLIANT	
Common Path of Travel	100'	14.2.5.3.2	15.2.5.3.2	COMPLIANT	
Travel Distance to Exit	200'	14.2.6.2	15.2.6.2	COMPLIANT	
Windows for Rescue	No	14.2.11.1.2(2)	15.2.11.1.2(2)	SPRINK. EXCEPT.	

Refer to Code Plan for Egress, Exit Access, Maximum Travel, Maximum Common Path and Maximum Dead End Corridor.

	Hours			Hours	
Exit Stairs	1		Hazardous Rooms		
Shafts	1		Boiler Room	SPRINKLER	15.3.2.1
Horizontal Assemblies	1		Storage Room	SPRINKLER	15.3.2.1
Exit Access Corridors	S	14.3.6(2)	Janitor Closet	SPRINKLER	15.3.2.1
Smoke Compatments	N/A	14.3.7.2(2)			

See Code Plan for locations of rated partitions.

INTERIOR FINISHES	
Allowable Finishes	Class
Exits and Exit Passageways	Α
Exit Access Corridors	В
Other Areas	С

BUILDING DATA					
Use and Occupancy	v Classification				
Building A	Primary Use	Е		Number of Stories	3
Fire Area #1	Accessory Use	Α		Height	45 LF
	Accessory Use	В	ď	1st Floor	5032 SF
	•		Area	2nd Floor	4966 SF
	Mixed Use	No	⋖	3rd Floor	4966
	Construction Type	3b		Footprint	5032 LF
	Sprinklers	Yes		Perimeter	316 LF
	Building Type	S1		Frontage	290 LF
				Weighted Width	30.0 LF
This Fire Area	does	Meet Code for Heigh	This Fire Area	is	Within Allowable Area
Building B	Primary Use	A-3		Number of Stories	1
Fire Area #2	Accessory Use	Е		Height	24.00 LF
			m	First Floor	12712 SF
			Area		0
	Mixed Use	No	٩		0
	Construction Type	5b		Footprint	12712 LF
	Sprinklers	Yes		Perimeter	562.5 LF
	Building Type	S1		Frontage	488 LF
				Weighted Width	30 LF
This Fire Area	does	Meet Code for Heigh	This Fire Area	is	Within Allowable Area
Building C	Primary Use	Е		Number of Stories	0
Fire Area #3	Accessory Use	_	Area	Height	0 LF
1 110 7 11 00 110	7 loodoodly GGG		71100	First Floor	0 SF
					0
	Mixed Use	No			0
	Construction Type	5b		Footprint	0 LF
	Sprinklers	Yes		Perimeter	0 LF
	Building Type	S1		Frontage	0 LF
	ballaling Type	31		Weighted Width	#DIV/0! LF
This Fire Area	does	Meet Code for Heigh	This Fire Area	#DIV/0!	Within Allowable Area
		Fire Area #1	Fire Area #2	Fire Area #3	
Separated Uses		0	0	1 110 / 116a #0	
Fire Alarm System		Yes	Yes		
Existing Building Alt	eration Level	. 55	. 55		1, 2, 3
CONSTRUCTION CL	ASSIFICATION				_
Table 601		Fire Area #1	Fire Area #2	Fire Area #3	
		3b	5b	5b	
Element		Rating	Rating	Rating	
Primary Structural F	rame	0	0	0	
Bearing Walls	Exterior	0	0	0	
ū	Interior	0	0	0	
Non Bearing	Exterior	0	0	0	
Ŭ	Interior	0	0	0	
Floors		0	0	0	
Roofs		0	0	0	
See Code Plan for lo	ocations of rated par	titions.			
PROTECTION					
	Hours		Incidental Rooms	Hours	

	Hours		Incidental Rooms	Hours
Exterior Walls	0	Table 602	Table 508.2.5	
Firewalls	2	Table 706.4	Boiler Room	1
Fire Barriers	1	Table 707.3.9	Sprinkler Room	1
Shafts	1	708.4		
Fire Partitions	1	709.1		
Exit Stairs	1	708		
Horiz. Assemblies	1	712		
Exit Access	Smoke	1018.1		

See Code Plan for locations of rated partitions.

INIT	EDI	\cap P	FIN	ISHE	9

Allowable Finishes Table 803.9	Fire Area #1	Fire Area #2	Fire Area #3
Exits and Exit Passageways	В В		В
Exit Access Corridors	С	С	С
Other Areas	С	С	С

OCCUPANT LOAD

Classification	1004.1.1				
		Building A	Building B	Building C	Total
Educational					351
Classrooms	20sf/person gross	336			
Library (Reading)	50sf/person net	10			
Library (Stacks)	100sf/person gross	5			
Assembly					882
Non-Concentrate	15sf/person net		0		
Concentrated	7sf/person net		816		
Stage	15sf/person net		66		
Locker room	50sf/person				
Business		0			14
Offices	100sf/person gross	13			
Kitchen	200sf/ person gross	0	1		
Storage & Mech.	300sf/ person	0			
	TOTAL	364	883	0	1247

Refer to Code Plan for Egress, Exit Access, Maximum Travel, Maximum Common Path and Maximum Dead End Corridor.

MEANS OF EGRESS

		Required		Provided/Worst Case
Number of Exits	Under 49 occ.	1	1006.2.1	1
	Over 49 under 500	2	1006.2.1	2
	Over 500 under 100	3	1006.2.1.1	3
Common Path of Travel		75	Table 1006.2.1	46
Exit Access Travel Distance		250	Table 1017.2	141
Dead End Corridor		50	1020.4(2)	16

PLUMBING REQUIREMENTS

	O	Required	2902.1	0.	5	0 . 0 .
	Classification	Water Closets	Lavatories	Showers	Drinking Fountains	Service Sink
Primary Use	E	8	8	-	4	1
Accessory Use	Α				2	1
	Men	4	3	-		
	Women	7	3	-		
	В	1	1	-	1	1

Primary Use E Accessory Use A Men Women

Provided Water Closets	Lavatories	Showers	Drinking Fountains	Service Sink
8	6	1	0	0
			0	
1	1	-		
1	1	-		
1	1	-	0	

NON-COMPLIANT NON-COMPLIANT COMPLIANT

NON-COMPLIANT NON-COMPLIANT

Uses are not subject to simultaneous occpancy so therefore fixtures can be shared between uses. This does require that toilet facilities in other parts of the building from the gymnasium be open when the gym is in use.

ENERGY CODE

Using Prescriptive Method for compliance

В

	·	Required	Provided	
Roof	(Attic and Other)	R-30ci	COMPLIANT	Only in 1996 addition. NON-COMPLIANT elsewhere
Walls	(Wood Framed)	R-11.4ci	COMPLIANT	Only in 1996 addition. NON-COMPLIANT elsewhere
Bewlow Grade		R-7.5ci	COMPLIANT	Only in 1996 addition. NON-COMPLIANT elsewhere
Heated Slabs		R-15 for 24"	N/A	
Doors		U-0.70	NON-COMPLIANT	Unknown
Windows		U-0.35	NON-COMPLIANT	Unknown

Troy Elementary School **Existing Building Needs**

> 1st Floor
> 2nd Floor
> Total
>
>
> 17,674
> 4,962
> 22,636
>
>
> 280
> 1,415
> 1,695
> Area Perimeter

					Cost /	Priority	
Cat	ltem	Existing Descriptions	Corrective Measure	High	Medium	Low	Future
Site	Minimum Size Lot Water and Septic Bus/Car Separation Parking Playground/Playfields Site Features Grading/Drainage	The lot has acrage but much of it down a steep slope. Water and Sewer is on the town municipal system. Car pick up is separated but parking is not. The roof is easily accessible from the ground. Fencing has been installed but it is in disrepair. It is worth investigating.	Create a new means of previnting access to the school roof.		\$ 25,000		
90	8 Oil, Propane Tank Age/Condition 9 Roof Condition	Fairly new buried propane tanks. Existing slate largely in good condition but some areas require attention. Gym roof in poor condition.	Repair slate and add metal edging. Replace gym roof. Repair damaged roof edges, repaint trim. Replace 1970s roof.	\$ 100,000		\$ 65,000	
Envelope	 10 Wall Condition (insulation and moisture protection) 11 Door Condition (energy efficiency and operation) 12 Window Condition (energy efficiency and operation) 13 Foundation Condition (insulation and moisture protection) 	Most of the windows are past their life expectancy. The existing stone foundation has some moisture issues. The area outside the administrative offices is partially below grade and has moisture issues.	Replace the windows. Install new drainage and possibly regrade.	\$ 300,000 \$ 50,000			
Life Safety	14 K-2 location based on LED 15 Panic devices 16 Stair Details (Rise/Run, Railings) 17 Areas of Refuge 18 Capacity of Means of Egress 19 Corridor Width 20 Number of Exits 21 Dead-end Corridors 22 Exits through Intervening Rooms 23 Door Arrangement 24 Travel Distance 25 Means of Escape	Exterior fire escape stairs are in disrepair and not code compliant.	Replace steel platforms and stairs.		\$ 50,000		
	26 Protection of Vertical Openings 27 Protection of Hazards 28 Protection of Corridors 29 Smoke Compartments 30 Fire Alarm, Emergency lights and Exit lighting 31 Furnishings, Decorations and Personal Effects in the Corridor	Original building was not designed to have the stairs separated. Retrofits have been compromised and themselves do not meet code. The main fire alarm panel is new.	Investigate ways to reconfigure for better egress and fire separation.		\$ 60,000		
Building Code	32 Height and Area Limitations 33 Construction Classification 34 Fire Rated Construction	The heilding has a second control of the sec					
uctural Buil	35 Sprinklers36 Fire Protection37 Snow Load Capacity38 Wall Condition (seismic capacity, cracks or deflection)	The building has an automatic sprinkler system. Canopies show structural damage.	Rebuild canopies.		\$ 30,000		
Struct	39 Floor Load Capacity 40 Foundation Condition (cracks or rot)						
ibility	41 Parking 42 Building Access 43 Accessible Route 44 Clearances	None. The building Access is through a side door. The accessible route through the building is maintaned through a stair lift. Some classroom doors do not have proper clearances.	Build a new front entrance that is handicap accessible. Configure new entrance with elevator and connection to all levels.			\$ 250,000 \$ 750,000	
Accessibility	45 Door Hardware 46 Stair Details 47 Toilet Facilities 48 Signage 49 Elevator	No toilet facilities in the building are fully handicap accessible. No elevator exists. Current accessibility relies on a	Renovate toilet roomf to bring into full compliance.		\$ 175,000	\$ 175,000	
Indoor Environmental Quality	50 Ventilation 51 Thermal Control 52 Moisture / Mold 53 Lighting Quality 54 Acoustics	stair lift. Ventilation and cooling is minimal. Control system is archaic. The lighting appears to be currently adequate. Some issues with noise between classrooms.	Upgrade HVAC. Upgrade to digital controls. Add insulation in walls.	\$ 350,000	\$ 150,000	\$ 20,000	
Build. Services	55 Sanitation 56 Boiler Condition and Distribution 57 Water Supply 58 Plumbing / Fixture Count 59 Kitchen Equipment 60 Main Electrical Service	The boiler is in relatively good condition. Some fixutures are archaic. The kitchen is considerably undersized. Main panels are about 15 years old and in good condition. No generator.	Replace old toilet fixtures. Upgrade and expand the kitchen.			\$ 250,000	
Build.	62 Power Distribution 63 Lighting Efficiency 64 Site lighting 65 Roof Drains 66 Phone, Intercom, Security	Outlets are aging and quantity low for technology. Lighting is older and energy inefficient. ??? The phone and intercom are aging.	Upgrade outlets. Replace with LED lights. Add LED site lights for safety and security. Replace phone and intercom with an integrated VOIP system.		\$ 22,000	\$ 225,000 \$ 20,000 \$ 25,000	
Interior	67 Ceilings 68 Walls 69 Floors 70 Doors	The gymnasium has a type of ceiling that is hard to replace and over time has become damaged. Ceilings elsewhere are also in poor condition. Walls in the oldest part are lath and plaster. The flooring in the original building shows wear. Other strucural issues may also exist.	Replace gymnasium ceiling. Replace ceilings in entire	\$ 100,000	\$ 60,000	\$ 90,000 \$ 25,000	
	71 Cabinetry 72 Fixed Equipment 73 Visual Display Boards	Most classrooms do not have cabinets. The visual display board are aging.	Add cabinets to match district standard. Change boards that are in poor condition and add smart TV's to match district standard.		\$ 56,000 \$ 21,000		
Security and Safety	 74 Lock-down of public areas 75 Secure Visitor Check-in 76 Technology 77 Physical Hazards 78 Hazardous Materials 79 Visibility 	The gymnasium can be separated from most but not all classrooms. The current main entrace is close to main office but not secure from the corridor. School has cameras. The approach and parking is not visible from the main office.	Create new vestibule that is locked with a direct window to the main office.	\$ 120,000			
Miscelaneous	80 81 82 83 84 85						
				\$ 1,020,000	\$ 649,000	\$ 1,895,000 \$	\$ -

TTG Study Recommendations Changes to TTG Study Barker Architects Recommendations

Total Renovations \$ 3,564,000

State Funding Thresholds \$

 Cost
 Existing
 Minimum
 Maximum

 178
 \$ 4,029,208
 \$ 1,007,302
 \$ 2,417,525

Troy Elementary School

Curriculum Worksheet

Design Capacity	200
Core Capacity (Theoretical Max.)	300
Periods Per Day	6
Number of grades (include K)	7

Max.

		Students/			Students/			Teaching	
<u>Subject</u>		grade	Avg. Size		grade	Max Size		Stations	
Pre-Kinde	rgarten	9	16		18	18		1.0	
Kindergarten (1)		27	16		36	18		2.0	
General Cl	lassrooms								
1	Grade Classrooms	27	18		40	20	2.0		
2	Grade Classrooms	27	18		40	20	2.0		
3	Grade Classrooms	27	20		44	22	2.0		
4	Grade Classrooms	27	20		44	22	2.0		
	Grade Classrooms	27	22		48	24	2.0		
6	Grade Classrooms	27	22		48	24	2.0		
					General	Classroom	Total	12.0	
		% enrolled	Total	Max Size	Meetings / Week		k	Required Stations	
	d. /Specialists (2) ACES Title I OT / PT Speech Reading	20%	60	6		10		4.0	
	d Special Rooms Science								
	Art	100%	300	25		1		1.0	
	Music	100%	300	25		1		0.0	
	Phys. Ed.	100%	300	25		2		1.0	(3)

¹ Kindergarten is full day.

- Actual Special Ed and Specialists required spaces varies considerably from school to school.
- 2 Secialists include regular ed small group instruction. Above calculation is solely for computing purposes. Required spaces should be base on actual programs.
- 3 Gymnasium to be designed for 2 teachings stations simultaneously.

Avg.

4 Multi-Age classrooms employed to create more efficient class sizes.

Table E

Barker Architects, PLLC 11/17/2019

Troy Elementary School

Sq. Ft. / Student (Design Cap.) Sq. Ft. / Student (Core Cap.)

Space Needs Worksheet

Design Capacity 200 Core Capacity 300

	ELEMENT	DESIGN		EXISTING				COMMENT	
		#	SIZE	TOTAL	#	SIZE	TOTAL		
EDUCATIONAL SPACES	Pre-Kindergarten	1	1000	1000				0%	
	Kindergarten	2	1000	2000	2	812	1624		
	Classrooms	12	900	10800	9	682	6142	57%	Most classrooms are
			4000	4000		200	000	000/	considerably undersized.
9	Art Music	1	1000	1000	1	602	602	60%	
Y	IVIUSIC								Specialists are in regular
Š	Special Ed. /Specialists	4	360	1440	1	745	745	52%	education classrooms that
Ш									have been converted.
	Phys Ed			5600			5710	102%	
	Food Service			4500			0	00/	
	Caf. / Multi-Purpose Rm			1500			0	0%	
SPACES	Kitchen			700 1000			360 986		Kitchen very undersized.
AC	Assembly Library			1800			900 976	54%	
R	Stacks	1	1400	1000			970	54 %	Library undersized and not
CORE	Computer	1	400						located centrally.
8	Offices	·	100	1200			1533	128%	
	Admin./Guid.		900	1200		368	1000	12070	
	Faculty / Work		0			543			
	Nurse		300			622			
	Subtotal			28040			18678		
	MiscCirc, Mech, Toilets,		400/						Existing has higher
	Janitor Storage		40%	11216		48%	8920		net:gross ratio due to
	•								functional obsolescence
	Totals		l	39256		J	27598		
	Totalo			00200			21000		

196

131

Table F

Barker Architects, PLLC

138

92

11/17/2019